
And The same of th

The second secon



Survey No.

Survey Narrative To Comply With O.R.S. 209.250

Survey For:

John E. McCaw Jr. 5400 Carrillion Point Kirkland, WA 98033

Location:

The N.W. 1/4 and the S.W. 1/4 of S.4 and the N.E. 1/4 and the S.E. 1/4 of S.5 of

T.35 S., R.1 W., W.H., Jackson County, Oregon.

Purpose:

To survey and monument the tract of land shown on the annexed map according to the legal descriptions furnished in the

Preliminary Title Report.

Procedure:

The controlling Section and one-quarter Section corners were tied to in a closed traverse network and the location of the fractional section lines were calculated. The Southwest corner of Section 4 was found to be out of position as shown on Survey No. 5104 due to an apparent error in the measurement between the controlling corners to the East and West The position of this corner was determined in proportion to Original Government distances to the nearest controlling Section and one-quarter corners to the North, South, East and West.

The West line of the property along the river was determined to be the center of the river as it existed at the time of the original Government Survey in 1855. Due to such a large and perceptible change in the location of the river, the change was determined to be caused by avulsion. The property line was located under the rules governing avulsion, where the change of the channel does not change the boundary, but remains as it was in the center of the old channel.

in the center of the old channel.

The meander lines from the original Government survey in 1855 were proportioned and adjusted by Compass Rule and a mean of the meanders of the left and right banks was calculated. This mean was surveyed and monumented (where possible).

The Southerly line was established by holding the Deed distance and rotating the bearing to match the bearing of the North-South centerline of Section 4.

The right-of-way of Hammel Road was held as monumented by Survey No. 6795 and the curve data shown was calculated to fit existing monuments.

The monuments found and those set are as shown on the annexed map with the addition of a steel post set by each property corner monument.

set by each property corner mos

Basis of Bearing:

Survey No. 5104

Date:

November 29, 1989

T35S R1W SEC4 TL401,700 & 800

PROFESSIONAL LAND SURVEYOR

> OFEGON JULY 16, 1971 LARRY J. FRIAR 961

Larry J. Friar L.J. Friar & Associates P.C. Consulting Land Surveyors 717 West 10th, Suite 1 Medford, OR 97501 (503) 772-2782

5.00

91-00894

0000

AFFIDAVIT OF CORRECTION Pursuant to O.R.S. 209.255

I, Larry J. Friar, Registered Professional Land Surveyor of the State of Oregon No. 961, do hereby state that I have discovered a drafting error on that survey for John E. McCaw Jr., filed December 29,1989 as Survey No. 11855 in the Jackson County Surveyor's office.

The error is in the course running North $00^{0}17'38"$ East from the 1/4 Corner common to Sections 4 & 9 T.35 S., R.1 W., WM. The distances shown as 2247.36 and 420.61 should be 2237.46 feet and 430.56 feet respectively.

Surveyor

I Verlyn Thomas, Jackson County Surveyor, hereby certify that I have examined this Affidavit of Correction, and that the changes are permitted in accordance with O.R.S. 209.255.

Verlyn Thomas, Jackson Co.Surveyor

Jackson County, Oregon Recorded OFFICIAL RECORDS

11:14 JAN 1 4 1991 A M

CHEK and RECEPTION

PROFESSIONAL MAND SURVEYOR

> RESON JULY 16. 1971 ARRY J. FRIAR