

20984

**SURVEY MONUMENT REPLACEMENT RECORD**

Situating in Sections 18 and 19, T36S, R1W, W. M.

Jackson County, Oregon

December 12, 2011


Survey By: Richard L. Bath, PLS 1069

For: Urban Renewal Agency of Jackson County  
10 South Oakdale, Room #214, Medford, Oregon 97501Re: Filed Survey No. 20479 Horizontal Control and Monument Recovery for 11<sup>th</sup> Street (Ave "G" to Ave "A").

Due to construction activities which have disturbed and/or destroyed the locations of certain monuments shown on Filed Survey No. 20479, we have replaced said monuments as noted below.

Monuments replaced with a 5/8" x 24" rebar with an orange plastic cap stamped "HARDEY ENG. & ASSOC.", are numbered **257, 258, 259, 260, 261, 266, 267, 269, and 6263** as shown on said filed survey.Monuments replaced with a 5/8" x 24" rebar with a 1.5" diameter aluminum cap stamped "HARDEY ENG. & ASSOC.", are numbered **256 and 262** as shown on said filed survey.

Those destroyed monuments have been replaced in their record recovery positions as shown on Filed Survey No. 20479 and no analysis of the correctness of their location relative to a deed corner position has been made.



Richard L. Bath, PLS 1069

Director of Surveying

Hardey Engineering &amp; Associates, Inc.

2870 Nansen Drive

Medford, Oregon 97504

Ph. 541-772-6880

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR*Richard L. Bath*OREGON  
JULY 30, 1976  
RICHARD L. BATH  
No. 1069

RENEWS 12/31/13