


MAP OF SURVEY FOR

MRS. MADELINE POOLE 1731 MILL CREEK DR. PROSPECT, OR. 97536 SITUATED IN

N.E. 1/4, SEC. 11, T.33S., R.2E., W.M.
JACKSON COUNTY, OREGON

DETAIL A DEPICTS SURVEY TO DETERMINE NORTHWEST CORNER S.E. 1/4 - N.E. 1/4 SEC. II. DETAIL B DEPICTS SURVEY OF PARCEL DESCRIBED IN VOL. 570 - PG.6 OFFICIAL RECORDS AND PORTION OF ADJOINING PARCEL.

Marine State of the Control of the C



SURVEYOR

HAROLD L. CENTER P. L.S. 2604 DAVID LANE MEDFORD, OR. 97504



9916

33 2E 11

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209:250 OREGON REVISED STATUTES

Survey For:

Mrs. Madeline Poole 1731 Mill Creek Drive Prospect, Cr. 97540

Location:

Northeast One-quarter Section 11, Township 33 South, Range 2 East, Willamette Meridian Jackson County, Oregon

Basis of Bearing:

North-South centerline of Section 11 as established by the B.L.M. survey.

Purpose:

To establish the boundaries of that parcel of land described within Volume 570, Page 6 of the official records of Jackson County and a portion of the parcel situated to the West.

Procedure:

Performed a closed traverse tying the North, East and Center one-quarter corners and the Northeast section corner. From this control I computed the position of the Southeast corner of the Northwest one-quarter of the Northeast one-quarter said point being the point of begining for the tract described within Volume 570, Page 6. This survey is shown within 'Detail A' on the attached map of survey. I then proceeded to layout the boundaries of the tract described within Volume 570, Page 6 along with the parcel of land situated to the West of said parcel. Those parcels are shown within 'Detail B' on the attached map of survey.

* * RECEIVED * *

Date 3/29/81 BySk

This survey Consists of:

_______ sheet(s) Map

______ page(s) Marrative

JACKSON COUNTY

SURVEYOR

The mean centerline of Mill Creek Drive was tied at a distance Easterly and Westerly of the parcel and the bearing between said points utilized as the bearing of Mill Creek Drive. Monuments were set at a 30.00 foot offset and parallel to said centerline.

All controlling corner monuments recovered were found as described within the official B.L.M. record. All corner points were found in good condition with the exception of the Northeast section corner which was found to have all accessories removed or in a dead condition. I marked no new accessiries at this corner point as the corner is situated near several residences.

February 25, 1984

HAROLD L. CENTER
Registered Professional Land Surveyor
Oregon Certificate No. 1071
2604 David Lane
Medford, Or. 97504

PROFESSIONAL
LAND SURVEYOR

OREGON

OREGON

JULY 30 1974

HAROLD L CENTER

No. 1971