

T. 37 S. R 1 W
Section 19

431

WRITTEN NARRATIVE to accompany plat for survey No. 431

as specified by Oregon law.

SURVEY FOR R.E. MC INTIRE, Medford, Oregon.

PURPOSE, to locate or re-establish lot corners on East and North side of Block 3, and Lot 5 Block 5 Lake Wood Subdivision Jackson County, Oregon.

Survey Made April, 1952.

PROCEDURE, All Original pipe corners found on the East side of Block 3 except the corner between lots 7 and 8, all corners out on the north side of Block 3 except the block corner at the Northwest corner of Block. With these controls already in I set the point temporarily at the Northeast corner of Block 3 and turned an angle check, then set all missing pins as shown on the plat.

For Lot 5 Block 5, all rear pins in good order, also found the West pin between lots 4 and 3, with this information I then set 5/8 x 30" steel rods for the three front corners of Lot 5 as shown on the plat.

