10092

(TL 107) 38 1529

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250.

SURVEY FOR: Ronell R. Yates & Judith E. Yates

Randall G. Stroh & Bonnie H. Stroh

1590 Butler Creek Road

Ashland, Oregon

SURVEY BY: Boyden Surveyors

108 Mistletoe Street

Medford, Oregon

LOCATION: NE 1/4 of Section 29 and D.L.C. No.44

T. 38 S. R 1 E., W. M.

DATE: October 19, 1984

BASIS OF BEARINGS: Oregon co-ord system (South zone) from

pin # 47 to T-104 per Filed Survey No. 5011, with grid bearings decreased in Azimuth by

 $\Theta = 1^{\circ} 31' 10".$ 

A survey of the purchase tract (See Instrument **PURPOSE:** 

No. 84-16407, O. R.) revealed discrepancies with the existing fence lines along the North and South property boundaries. The existing fence lines were monumented as shown and "Boundary line agreement"

descriptions were furnished the Strohs for processing. Also the boundary line agreement described in

Instrument No. 67-06691, O. R.) as monumented on Filed Survey No. 3526 was projected Northerly and boundary line agreement descriptions prepared for processing withthe adjoining owners to the West. The recording of these proposed boundary line

agreements between the Strohs and the adjoining owners


will then fix the final property boundaries as

established and monumented on this survey.

PROCEDURE: Utilizing E. D. M. and related equipment, found

monuments as indicated and set proposed boundary corners at positions shown on the annexed map.

> \* RECEIVED \* Date 10/19/BY BYSK This survey Consists of \_\_\_\_ sheet(s) Map \_ page(s)Narrati🖦 JACKSON COUNTY **SURVEYOR**



SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR: HOUSING AUTHORITY OF JACKSON COUNTY

2231 TABLE ROCK ROAD MEDFORD, OR 97501

LOCATION: LOCATED IN DONATION LAND CLAIM NO.60 IN THE SOUTH-

EAST ONE-QUARTER OF SECTION 13, TOWNSHIP 37 SOUTH, RANGE 2 WEST, WILLAMETTE MERIDIAN, JACKSON COUNTY,

OREGON.

TO ESTABLISH A LINE FOR A PROPOSED FUTURE PARCEL PURPOSE:

AS REQUESTED BY THE CLIENT.

FOUND PINS THAT WERE SET AND/OR USED DURING SURVEYS PROCEDURE:

NO. 4669, 6830 AND 8834. THE 3/4 INCH IRON PINS AT THE NORTHEAST CORNER AND THE SOUTHEAST CORNER OF THE PROPERTY SURVEYED DURING SURVEYS 4669 AND 8834 ARE UNDER A CONCRETE SIDEWALK. THE 3/4 INCH PIN AT THE NORTHEAST CORNER WAS UNCOVERED, REFERENCED AND A TACK IN A LEAD PLUG WAS SET IN THE SIDEWALK OVER SAID PIN. THE 3/4 INCH PIN AT THE SOUTHEAST CORNER COULD NOT BE UNCOVERED WITHOUT DESTROYING THE SIDE-WALK, SAID CORNER WAS RELOCATED FROM INFORMATION

USED DURING MY SURVEY NO. 6830 AND A TACK IN A

LEAD PLUG WAS SET.

\* RECEIVED \* \*

Date 10/26/84 BySk

This survey Consists of: \_\_\_\_\_ sheet(s) Map

↓ page(s) Narrative

JACKSON COUNTY **SURVEYOR** 

DATE: OCTOBER, 1984

> FRIAR-MOFFIT & ASSOC. 717 W. 10TH ST. MEDFORD, OR 97501

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 17, 1970 LOYD R. MOFNIT 944