

SWAIN SURVEYING, INC.

27½ North Main Street, Suite 9 ASHLAND, OREGON 97520

SURVEY NO. 10456

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209 250 OREGON REVISED STATUTES

SURVEY FOR:

Valley of the Rogue Bank

William Butler

P.O. Box 36

2082 Coker Butte Road

Ashland, OR 97520

Medford, OR 97504

LOCATION:

Situated in Lots 2,3,8 and a portion of Lot 4 in Block 22 of the Chitwood Tracts, Lots 1 thru 9 in Block V of the Railroad Addition in the City of Ashland and a portion of an alley vacated by Ordinance No. 412 all in Donation Land Claims No. 40 and 42 in the Northwest quarter of Section 9, Township 39 South, Range 1 East of the Willamette

Base and Meridian, Jackson County, Oregon.

PURPOSE:

To survey the boundary lines of William Butler and Valley of the Rogue Bank ownership. Adjust the boundary lines of said ownerships to the parcel configuration as shown on the accomapnying map and monument said boundary lines as shown thereon. No legal descriptions

have been prepared at this time.

PROCEDURE:

Initiated a new control traverse line tieing into previous control traverse lines established while conducting Recorded Surveys No. 5802, 8098 and other numerous surveys throughout the general area. At the intersection of North Pioneer and Spring Street, new curb and sidewalk construction has destroyed all but one of the original lead shot reference points per City of Ashland Field Book No. 5, page 76. These reference points had been found by this surveying firm many years ago and tied to our control traverse line at that time. In establishing the final location for the centerline intersection point of North Pioneer and Spring Street, the results shows a found 5/8 inch iron rod to be out of harmony with its reported location. Therefore, it was not utilized for street centerline control.

In establishing the centerline of Spring Street it became apparent that a difference in measurement between this surveyor and Recorded Survey No. 8224 exist. At the location of the reference points taken by Mc Kissick, City of Ashland Surveyor, and shown in City Field Book No. 20 at page 19 in the year 1911, a lead shot was found in the Northerly and Southerly concrete curb. In the street, two (2) hub tacks were found some 0.03 foot apart at the approximate centerline of Spring Street. These two (2) reference points (lead shot) were found by this surveyor many years ago and our present ties verify the ties and calculations made at the time of our first visit. An iron bar monument was set by M.L. McCall at the centerline of Spring Street at the East boundary line of Donation Land Claim No. 40 in the establishment of the Official City of Ashland Survey approved and adopted by the Common Council of the City of Ashland on the 5th day of November, 1888. Recorded Survey No. 8224 shows finding a 1 1/4 inch square bolt at this location. Years ago, before the paving overlay of this street, a monument was found at this same approximate location and was thought to be a 1 inch square iron bar. Due to the fact Recorded Survey No. 8224 needed the Easterly boundary line of Donation Land Claim No. 40, but choose to set witness corners instead and also shows this point as an angle point in the centerline of Spring Street, prompted further investigation of this found monument. First of all, the distance from the computed centerline intersection of North Pioneer and Spring Street to the found monument in question is within 0.1 foot, more or less, of the distance called for by M. L. McCall. However, in looking at the returned bearings of said street, it is my opinion that someone, at a point in time after M.L. McCall, tried to reset this corner point and failed to establish the proper alignment by approximately six (6) minutes of meridian. Anyway, this

Valley of the Rogue Bank - William Butler page 2

found monument in question was evaluated in relation to its departure position to the Fasterly boundary line of Donation Land Claim No. 40. It was found to be out of harmony by an amount which would not allow it to control the direction of said claim line. However, in checking this found monument in relation to the centerline of Spring Street, as controlled by the found reference points of McKissick's on the Easterly end and by the computed centerline intersection of North Pioneer and Spring Street, on the Westerly end, I cannot concur with Recorded Survey 8224 that an angle point exists at this point. I personally returned to the location of this monument and conducted an examination of this point. Without extensive excavation around this monument, it appeared to me that we are dealing with neither a bolt or an iron bar per say. It appears as though it could be some sort of an axle shalf. However, I'm not sure, so I have elected to describe it as shown on the accompanying map.

Some fence encroachments exist on the Southerly boundary line of Parcel No. 1 and fence encroachments exist along the Northerly boundary line of Parcel No. 2. The extent of these encroachments are as set forth on the accompanying map.

It should be noted that Chitwood Tracts and the Railroad Addition shows the Easterly boundary line of Donation Land Claim No. 40 controlling the boundary between said recorded subdivisions. In 1888 M.L. McCall surveyed 'A' Street and Ash Street. In establishing the centerline of Ash Street, McCall calls for "to iron pin on East line of Donation Land Claim No. 40". He continues on to a "stone monument on centerline of 'A' Street." The iron pin set by McCall was found and checked for departure in relation to the line connecting the Southeast corner of Donation Land Claim No. 40 with the Ell corner Northerly thereof. The location of said iron pin and the nail in concrete in a monument case at East Main and the reported East line of claim No. 40 are within reasonable limits and nearly the same offset from the overall claim line. Therefore, the monuments as shown on the accompanying map were held for the East boundary line of Donation Land Claim No. 40 in this case. However, the found monuments along the centerline of 'A' Street, (North-South section) as now exist, are out of alignment. McCall's 1888 survey of 'A' Street shows a distance of 143 feet from 1st Street to a stone monument Westerly thereof. McKissick shows a distance of 148.1 feet. This problem was not resolved. The East boundary line of Donation Land Claim No. 40 was utilized for control and the relationship of that portion of 'A' Street, which bears in a North-South direction, is shown for comparison. Other pertinent information is as shown on the accomapnying map.

BASIS OF BEARING:

True Meridian at the N-S centerline of Section 9 as derived from the National Oceanic and Atmospheric Administration (formerly Coast and Geodetic Survey) survey net established in 1968 and filed in the office of the Jackson County Surveyor.

PROFESSIONAL
LAND SURVEYOR

OR E'G ON
JULY 8, 1966
EVERETT L SWAIN
759

Swain Surveying, Inc. 27 1/2 N. Main Street Ashland, OR 97520

* * RECEIVED * *

Date 12/30/85 By 5

This survey Consists of
_____ sheet(s) Map
____ page(s) Narrative

JACKSON COUNTY
SURVEYOR

T.L. 13400 - 13500 - 13600 39 1E 9BA