

Sandana Carana property and the sand sandana and the sandana property and the sandana and the sandana and the

SURVEY NARRATIVE TO COMPLY WITH 0. R. S. 209.250.

FOR: Jerry P. and Joetta John 3565 Old Stage Road

Central Point, Oregon, 97502

BY: Boyden Surveyors 108 Mistletoe Street Medford, Oregon, 97501

LOCATION: SW 1/4 of Section 23, D. L. C. No. 60, T. 38 S.R. 1 W., W. M. and in the City of Talent, Oregon.

BASIS OF BEARINGS: From Aerial Mapping Co.aerial survey of 1970 for the Bear Creek Valley Sanitary Authority. Found 5/8" rebar/punch mark at traverse stations D-18 & D-19. From State Plane coordinates furnished the County Surveyor, converted the bearings to true by decreasing the azimuth by a computed theta angle of 1° 34' 12". Refinement of the coordinates was not considered in this conversion.

EQUIPMENT: NTD-4 and chain.

DATE: June 10, 1986.

PURPOSE: To monument, describe Parcels "A". "B" and "C" and prepare a MAJOR LAND PARTITION plat for recording with the Jackson County Clerk. For City of Talent approval, See File MLP-85-1, dated September 27, 1985.

PROCEDURE: Made ties to Government corners shown as re-established by the County Surveyor, and enclosed the desired tract by EDM traverse. Deed record distances Southerly from the South boundary of DLC 58, and record bearings of "East" were utilized for control of the overall North and South property boundaries. The boundaries at the Southeasterly corner of the overall tract were established by a recorded boundary line agreement as shown. The re-located Southwesterly right-of-way line of Front Street was established 80.0 feet Southwesterly at right angles from a mean average of the existing mainline railroad tracks. The overall Westerly tract boundary was established Deed Record distance Westerly from the Southeast corner of DLC 58. The Southerly terminus of said Westerly boundary, being on the North boundary of DLC 63, was left somewhat in doubt by Filed Survey No. 3066. The adjoining property to the West conveyed to the Phoenix School District No. 4 (See Instrument No. 70-00159, OR) refers to a 5/8"iron pin being 847.44 feet Westerly from the Northeast corner of DLC 63 (a distance derived by an old conveyance to David Brower recorded in Volume 25, Deeds, Page 538), yet Survey No. 3066 reports a distance of 849.80 feet and indicates a 5/8" rebar set. After finding said rebar in close proximity to the rebar set according to said Survey No. 3066, a search was made Easterly from the pin found to the pin called-for in said Instrument No. 70-00159 with negative results. The old fence corner falls even further East. The firm of Hoffbuhr and Associates, Inc. was contacted, wherein the original field notes and computations were examined. Neither survey firm could determine why the record-of-survey was changed from the Deeds. It was therefore determined to utilize the old deed calls for the Westerly boundary of the overall tract as the most-favorable solution at this writing. From said data, computed the corner positions and monumented same as shown on the plat to accompany this report.

\*\* RECEIVED \*\*

Date 8/3/86 By 5x

This survey Consists of:

\_\_\_\_\_\_\_ sheet(s) Map
\_\_\_\_\_\_ page(s) Narrative

JACKSON COUNTY
SHARLOR

PROFESSIONAL LAND SURVEYOR

Yan Dlaw

OREGON
JULY 16. 1967
GARY D. KAISER
NO. 803

Map No. 381W23CB, Tax Lot 500