

## BASIS OF BRARING:

True Meridian at the East boundary line of Section 8 as derived from the National Oceanic and Atmospheric Administration (formerly Coast and Geodetic Survey) survey net established in 1968 and filed in the office of the Jackson County Surveyor.

February 27, 1989

ref: MW1294T.NAR

Swain Surveying, Inc. 27 1/2 North Main Street Ashland, Oregon 97520

Tax Lot 200, 39-1E-8AB

PROFESSIONAL LAND SURVEYOR

SWAIN SURVEYING, INC.



27½ North Main Street Ashland, Oregon 97520

Survey No. 11536

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Margaret P., Wiley 200 Skycrest Drive Ashland, Oregon 97520

LOCATION:

Situated in the Northeast Quarter of Section 8, Township 39 South, Range 1 East of the Willamette Base and Meridian, Jackson County, Oregon.

PURPOSE:

To Partition into three parcels of land, the present ownership of Margaret P. Wileys' being known as Tax Lot 200, Assessor's Map 39-1E-8AB. Prepare four legal descriptions. One for each parcel and one for the total outer boundary of all three parcels.

PROCKDURK:

Extended the survey control of Recorded Survey No. 7933 into the area of concern and monumented the Parcels of land as shown on the accompanying map.

In reviewing the LOGAN DRIVE SUBDIVISION, a Planned Unit Development, Phase I, as now recorded, there becomes several questions which appear to me to have been ignored or overlooked. Some 10 to 15 years ago I made a search of the deed records pertaining to the title of the property, then owned by the Fowler's. Even though the Fowler's deed called into the North-South sixteenth line of the Northeast quarter of Section 8, the chain of title did not appear to support that document. When M.L. McCall surveyed property, of which the Fowler tract was a part, neither his field notes, nor did the previous deed record, call for the sixteenth line; therefore, unless a Quit Claim Deed or a Suit to Quiet Tile has been executed to cure the obvious hiatus, it still exist and no title company inserted calls to the sixteenth line will erase that fact. Also, the Southerly boundary line of the Logan Drive P.U.D. appears to have a similar problem. There appears to be a large hiatus there also. Here again a deed record call for an adjoiner cannot overcome the fact of a possible third party ownership which was not properly extinguished before utilizing that adjoiner Much additional research should be undertaken before any conclusions are made. Also, several discrepancies were found on the filed plat of the Logan Drive P.U.D. Some of these are as shown on the accompanying map.

According to the narrative accompanying the filed plat of the Logan Drive Subdivision, a Planned Unit Development, Phase I, to the City of Ashland, the Surveyor of record and the present landowner of the Logan Drive Development has accepted the boundary line as established on Recorded Survey No. 7933 where common to the Margaret P. Wiley ownership. This boundary line is again utilized in this survey.