

- ⊙ Indicates Jackson County Surveyor's Brass Cap Monument & Accessories Found.
 - Indicates 1 1/2" Iron Pipe Monument per R.S. N° 5104 Found.
 - Indicates 5/8"x 30" Re-bar w/ yellow plastic cap mkd. "TEMPLIN RLS 2359" Set.
- Bearings based upon the South line of Section 4, between the SW and S1/4 Corners per R.S. N° 5104.
- () Record bearing-distance per R.S. (Recorded Survey)

RECEIVED
 Date 3-16-89 By
 This Survey Consists of
 1 Sheet Map
 1 Record Narrative
 10x14" Plans

RICHARD TEMPLIN LAND SURVEYING
 2042 SANDRA PL. 776-0991 MEDFORD, OREGON

PLAT of SURVEY
 LOCATED IN
 SE. 1/4 of Section 4, T. 35S, R. 1W, W.M., Jackson County, Oregon
 SURVEYED FOR: Mr. G. SMITH DATE: MARCH 16, 1989
 SANTA MARIA, CA. SCALE: 1" = 200'

Mr. G. Smith

RICHARD G. TEMPLIN
PROFESSIONAL LAND SURVEYOR

2042 Sandra Pl.
Medford, Oregon 97504
(503) 776-0991

SURVEY FOR: Mr. Gene Smith
4798 Pleasant Pl.
Santa Maria, Ca. 93455

SURVEY NO. 11540



Location: Located in the Southeast Quarter of Section
4, Township 35 South, Range 1 West, Willamette
Meridian, Jackson County, Oregon.

Purpose: To monument those particular corners as shown
on accompanied plat per O.R. 86-06831.
The physical center of Hammel Irrigation ditch
was used to establish the westerly boundary as
there is no legal description of said ditch at
this time.

Date: March 16, 1988

Basis of
Bearing: The South line of Section 4, between the S.W.
and South 1/4 corners per Recorded Survey 5104

Procedure: Utilizing a Wild T-2, Wild T-16 and Mac 1E
EDM. Tied in the N.E., S.E., S.W., N.W. Section
Corners along with the East 1/4, South 1/4 and
North 1/4 Corners. The original West 1/4
Corner lands in the Rogue River now, so I
proportion a calculated position for it. From
this information I calculated the Section
breakdown as shown on accompanied plat.



R. G. Templin

