

SW Sec. Cor 22 1" G.I.P. with 2 1/2" brass cap from which bears;

24" D. Fir, brs. N18°50'E 53.53 ft. (Rec. N20°E 52.9 ft.)
14" D. Fir, brs. S79°40'E 21.53 ft. (Rec. S79°E 22.0 ft.)
27" D. Fir stump, brs. S21°40'E 24.43 ft. (Rec. N21°W 24.0 ft.)
15" Madrone, brs. S9°29'W 21.67 ft. (Rec. S10°W 21.7 ft.)
4" D. Fir, brs. S68°33'W 12.91 ft. (Rec. S68°30'W 13.1 ft.)
11" B. Oak, brs. N36°57'W 31.67 ft. (Rec. N35°W 32.1 ft.)

SW Cor DLC No. 37, 1" iron pipe with 2 1/2" brass cap from which bears;

14" W. Oak, brs. S8°47'W 131.54 ft. (Rec. S8°45'W 131.61 ft.)
5/8" iron pin, brs. S77°01'39"E 20.81 ft. (Rec. S77°03'E 20.81 ft.)
27" W. Oak, brs. N65°03'E 108.84 ft. (Rec. N65°22'E 108.79 ft.)
31" W. Oak, brs. S27°33'E 99.47 ft. (Rec. S27°26'E 100.17 ft.)

Bearing is based on the west line of D.L.C. No. 37 as per Filed Survey No. 598.

Surveyed by: Farber Surveying

P.O. Box 5286

Central Point, Oregon 97502

Date: November 1, 1990

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 26, 1985 HERBERT A. FARBER 2189

If went to t

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

Survey for:

John A. Jaksch, III and Carol A. Jaksch 13418 Sand Rock Ct.

Chantilly, Virginia 22021

Location:

Located in the southwest quarter of Section 22, Township 36 South, Range 3 West of the Willamette Meridian, Jackson County, Oregon.

Purpose:

To survey and monument the minor partition as shown on the accompanying plat as per the approval by the Jackson County Department of Planning and Development as File No. 89-5-MP. The new dividing line in this partition is along a zone line separating WR and EFU zones.

Procedure:

The found monuments shown on the accompanying plat were tied in a closed traverse. proportioned south quarter corner to Section 22 was computed from record information from the Donation Land Claim No. 37 survey executed by Sewall Truax in September 1855. The Township Subdivision was executed by Ives and Hyde in January 1855. The section corner to the east falls inside of the Donation Land Claim and in an agricultural field. This corner has been lost along with others in the vicinity. It is impractical to locate these government corners to locate a zone line on my Therefore a proportion clients property. position was used.

AND THE PROPERTY OF THE PROPER

The following easement deeds referred to in Instrument No. 75-07484 of the Official Records of Jackson County, Oregon were not found to be within the minor partition boundaries: Volume 30, Page 203, Volume 115, Page 440, Volume 421, Page 249 and Volume 481, Page 292 all of Deed Records of Jackson County, Oregon.

The following government corners were tied:

1/4 15/22

Brass cap in concrete 11" below the surface 34" easterly of the westerly edge of A/C of Highway 234, from which bears;

5/8" iron pin, brs. N27°28'31"W 54.50 ft. (Rec. N27°29'W 54.49 ft.) 18" W. Oak, brs. S63017'W 81.58 ft. (Rec. \$63015'W 81.1 ft.) 19" W. Oak, brs. N26°57'W 64.67 ft. (Rec. N25022'W 64.4 ft.) 5/8" iron pin, brs. S63°27'28"W 74.13 ft. (Rec. S63°24'W 74.13 ft.)

NW Cor DLC No. 37, 3/4" iron pin with a 2 1/2" brass cap exposed 2", as per July 30, 1981 re-establishment

1" G.I.P. with 2 2/1" brass cap as per March 1/4 21-22 23, 1989 re-establishment.