

Mail: 1140 ACACIA LANE GRANTS PASS, OR 97527

ROBERT M. THOMPSON

**TELEPHONE 476-3269** 

Office: 233 N. E. "B" STREET

Counsulting Engineer, Surveyor, Forester

13619

SURVEY TO LOCATE THE WEST, NORTH, AND EASTERLY BOUNDARIES OF THE CALVIN KINNEY PROPERTY IN THE SW4 SW4 OF SEC. 14, AND SE% SE% OF SEC. 15, T36S, R4W, W.M., JACKSON CO., OREGON

Narrative Description to comply with Par. 209.250, O.R.S.

hote I map sheet with this narrative)

BY:

Robert M. Thompson & Assoc., 1140 Acacia Ln., Grants Pass, OR 97527

FOR:

Calvin Kinney et al, 620 Wards Creek Rd., Roque River, OR 97537

PURPOSE:

As stated above.

PROCEDURE: The legal description furnished (by Mr. Kinney) made his property's Easterly line dependent on the Westerly line of O.R. 73-04161, which in turn was tied to the Westerly line and Northwest corner of properties described in O.R. 71-13406 and 71-13407. There is a substantial difference in bearing basis between past surveys, and deed records along the last said Westerly line. Using information from Survey Nos. (S/N's) 4608, 7964, 9104, 5690, and 6641, I surveyed and computed the corner locations and boundaries of the Kinney property. It is notable that the deed record Northwesterly corner of the O.R. 73-04161 property falls 27.62 feet Southwesterly of the extension of a fence, bearing S 28 12 33" E, said fence apparently intended for the Westerly line of said O.R. 73-04161. At the Southern extremity of said fence, on the approximate South line of Section 14, a found green steel fence post - in dense brush, appeared to be someone's (unrecorded) best effort at establishing the said O.R. 73-04161 southwest corner. Said corner location being indeterminate of accurate computation, I accepted said metal post as a witness corner. The Kinney Northwest corner, and Northeast witness corner, were then set as shown on my map. "Glo-top" stakes were then set on the Kinney North boundary, in conflict with a newly-built fence, of erratic alignment. Being the closest to the Kinney property, the East property line of O.R. 73-04770, monumented

The <u>corner of Sections 14,15,22 and 23</u> was found to be a flush CS 1981 brass cap at the corner of fences bearing Westerly and Southerly, and B.T's:

36" W. Oak N 7940W 82.2' w/healed faces, O.B.T

by S/N 5690 (also used by S/N 6641) was used for a bearing basis.

10" +/- W. Oak flush cut stump w/sprouts, S  $11^0$ W 11.5' 20" Madronna S  $19^0$ E 39.1' w/healed faces

June 28, 1993

LAND SURVEYING

\* \* RECEIVED \* \* Date. 8-9-93 By BE This survey Consists of: 1\_ sheet(s) Map <u>L</u> page(s) Narrative JACKSON COUNTY SURVEYOR BRIDGES ROADS

MENT M. THOMPSO

EXP. 12-31-95

DAMS

TRACT DESIGN

FOREST MANAGEMENT

TIMBER CRUISING AND APPRAISAL