

GARY D. KAISER R.P.L.S. ORE. 803 C.W.R.E. ORE. 73

## KAISER SURVEYING

19440 HIGHWAY 62 EAGLE PO!NT, OREGON 97524 PHONE SHADY COVE (503) 878-3995 Fax (503) 878-3995

SURVEY NO.

14608

SURVEY MARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR:

SUSAN SHOEMAKER

9180 SOUTH FORK OF BUTTE CREEK ROAD

EAGLE POINT, OR 97524

SURVEY BY:

KAISER SURVEYING

1944Ø HWY. 62

EAGLE POINT, OR 97524

LOCATION:

NE % of Section 13, T. 37 S.,

R. 2 E., W.M., Jackson County,

Oregon

BASIS OF BEARINGS:

Filed Survey No. 5789 (East bdry.

Section 13)

DATE:

July 24, 1995

PURPOSE:

To monument and described a tract to be conveyed to Jackson County for additional right-of-way for the South Fork of Little Butte Creek (County) Road to provide access to tract described in Instrument No.

83-10074 O.R..

PROCEDURE:

Utilizing EDM equipment made field

ties to existing BLM sectional monuments as shown and determined a position for the North quarter corner BLM monument from information on Filed Surveys 5789 and 11810.

Some question (stemming from Filed Survey No. 11810) as to whether the Thielsens re-established section corner (originally set by McCall in 1881) for the corner common to Sections 12, 13, 7 and 18 should be used for the Northeast corner of Section 13. This question is based on the 1882 factional survey of part of T. 37 S., R. 2 E., by Turner where he indicates he set a stone for the corner in question 1.80 chains South from the McCall corner, Turner also states he destroyed the McCall corner. A note on the narrative of Filed Survey No. 11810 states an opinion from the BLM as to the status of this corner was requested. I contacted Terry Nickerson, BLM Cadastral Surveyor, who indicated he was never notified on this matter, but the state office was aware of the question raiser on Filed Survey No. 11810. Nickerson

stated the state office questions whether Turner even set the stone for the NE corner of Section 13 since it has never been found and also since the McCall corner was not destroyed. In checking surveys of record I notice Turners distance on the West boundary of 13 were very short which could attribute to the reason he came in South of the NE corner, Nickerson agrees and stated Turners work in this area does not appear to be of a quality to be changing McCalls record and that it is the opinion of the State BLM office that Thielsens reestablish corner set by McCall in 1881 is the Northeast corner of Section 13 until somebody finds Turners stone.

The West boundary of the tract described in Inst. No. 78-00426 O.R. was located as shown on the accompanying map and the desired tract was monumented as shown.

