



20991

CEN. 1/4 COR. SEC. 30
Fd. 5/8" I. Pin per R.S.
No. 6065



SCALE 1"=50'
Basis of Bearings R.S. No. 14216

LEGEND

- ⊙ = Set 5/8" x 24" I. Pin (tagged RL.S 638)
- = Found 1" iron Pipe per R.S. No. 14216
- D.R. = Deed Record
- O.R.J.C.O. = Official Records Jackson County Oregon

REGISTERED
PROFESSIONAL
LAND SURVEYOR
George Burrell
OREGON
JULY 10, 1964
GEORGE R. BURRELL
638

Exp 12/31/97

A = N 2° 44' W 5.92
B = S 89° 22' 03" E 14.00
C = N 2° 44' W 26.01

ADJ. T.L. NO. 1800
38-1W-30
0.57 Ac.
Re: Dec. No. 97-42495 O.R.J.C.O.

T.L. NO. 1800
R.S. NO. 14216

MAP OF SURVEY
OF

PROPERTY LINE ADJUSTMENT located in
S.E. 1/4 of Section 30, Twp. 38S, R1W, W.M.
For: A.R. GRIFFIN
By: George Burrell, P.L.S., 1379
Brookdale, Medford, OR 97504
April 18, 1995
Revised Sept. 25, 1997

** RECEIVED **
Date: 12-11-97 By: [Signature]
This survey consists of:
1 sheet(s) Map
1 page(s) Narrative
JACKSON COUNTY
SURVEYOR

APPROVAL:
By: [Signature]
Jackson County Department of
Planning and Development
Date: 12-11-97, 1997
FILE NO. 97-214 PA

38 1W 30 TL 1300, 1400, 1800

15592

Survey narrative to comply with O.R.S. 209.250

For:

A.R. Griffin
Greenside Plaza Inc.
P.O. Box 1060
Winston, OR 97496

Location:

The Southeast one Quarter of Section 30, Township 38 South, Range 1W

Purpose:

To monument and describe an adjusted property boundary common to Tax Lots No. 1300, 1400 and 1800 as shown on the accompanying map.

Procedure:


This adjusted boundary was originally approved by County Planning in 1995 and was surveyed by me during 1995. The parties involved in 1995 were not able to complete the property line adjustment.

This year (1997) the parties re-applied and received County Planning approval for the adjustment. The Map of Survey was revised and is now being submitted for recording.

The found monuments of Recorded Surveys No. 6065, 6767 and 14216 were used as control in establishing the boundaries of tax lots no. 1300 and 1400 according to the procedure established by Recorded Survey No. 6065. The adjusted common boundary was located according to the clients instructions.

By:

George Burrell, P.L.S.
1379 Brookdale Ave.
Medford, OR 97504
Sept 25, 1997



renews 12/31/97

