16501 MAP OF SURVEY Located in the S.W. 1/4 of Sec. 4 & the N.W. 1/4 of Sec. 9 T.37S., R.2W., W.M., Jackson County, Oregon SURVEY FOR: SURVEY BY: Elizabeth Andersen L.J. Friar & Associates, P.C. (\$89°46 00°E \$89°46 06°E 560 00' = DR Consulting Land Surveyors 816 West Eighth Street Medford, Oregon 97501 Phone: (541) 772-2782 507 2nd Street N LINE DLC #45 PER F55471 Petaluma, CA 94952-5121 LEGEND: Found County Surveyor's brass capped monument and accessories. ● = Found 5/8" iron pin w/ plastic cap mkd. TEMPLIN LS2359 per FS14782. \bullet = Found 5/8" iron pin per FS5473. o = Set 5/8" x 24" iron pin with plastic cap mkd L.J. FRIAR & ASSOC ORJCO = Official Records of Jackson County, Oregon. FS = Filed Survey #. DOC #72-02557, ORJCO BASIS OF BEARINGS: Survey No. 5473 as shown hereon. UNDERGROUND TELEPHONE MARK FR NATE: December 1, 1999 UNIT OF MEASUREMENT: FEET | SCALE: 1"= 60" 589 40 06 E 175 00 38500 SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250 To survey and monument the subject property. PROCEDURE: Made ties to monuments as shown hereon. Held map record distance per FS9086 to position the alignment of the West line of DLC No.45. The centerline of Taylor Road as stated in Volume 2, Page 155 of County Road Records is to be held parallel to the North line of Section 9 running Wly. from the Northwest corner of DLC No.52. The R/W of Taylor Road per FS14782 differs from that of this Survey in that it utilized the constructed centerline of the road & not the DOC #80-13249, ORJCO centerline stated in the Road Records. The two differing opinions lead to a surveyed overlap of the North line of Doc #74-06368, ORJCO by some 10 feet. I could not find any other evidence other than the County Road Records that would persuade me to use the constructed centerline. The next issue of the subject property deals with the East property line. The subject tract calls to the West line of 0.0N Doc.#71-12616, ORJCO. The adjacent property to the East was FS5473 surveyed by FS5473 which was filed in 1973, but commenced in 1971. The narrative states that record lines were in dispute with the existing fence lines & that "the client was advised to obtain boundary line agreements". A subsequent deed (Doc.71-13017, ORJCO) used the data per FS5473 to call to the existing fence lines which were monumented by FS5473 As of this date, I can find no such calls to the existing fence lines for the subject tract surveyed herein. The client's POWER TRANSFURMER representative was notified of both of these concerns. The REPORTED BY CLIENT TO FEED POWER TO remaining property lines were computed using deed record THEIR PROPERTY distances & calls per Doc.80-13249, ORJCO. Those monuments found as well as those set are as shown hereon. N LINE OF FS14782 N89°49 39 F LAND SURVEYOR JAMES E. HIBBS DOC #74-06368, ORJCO RENEWAL DATE 6-30-01 FS14782 N**89°**49'39"E BASIS OF BEARINGS 9 10 TAYLOR & PER V 2 P 115 COUNTY ROAD RECORDS N89°49`39"E * * RECEIVED * * DATE April 28,2000 BY CUP This survey consists of ____sheet(s) Map **0** page(s) Narrative/ JACKSON COUNTY SURVEYOR 372WU4 TL2200