

## Survey Monument Replacement Record

Situated in Sections 20 and 21, T36S, R1W, WM

Jackson County, Oregon

August 27, 2004

Survey by: Richard L. Bath, PLS 1069

For: Urban Renewal Agency of Jackson County  
10 South Oakdale, Room #214, Medford, Oregon, 97501

Re: Filed Survey No. 17805, Horizontal Control for Antelope Road (East)

Due to construction activities which have disturbed or destroyed the locations of certain found monuments shown on Filed Survey No. 17805, we have replaced those monuments as follows:

Monuments numbered **100, 102, 103, 104, 105, 106, 501, 677, and 679** have been replaced with a 1-1/4 inch brass disc set in concrete stamped "HEA - LS 1069"

Monument number **101** has been replaced with a 5/8" x 24" iron rebar with 1-1/4 inch aluminum cap stamped "HARDEY ENG. & ASSOC."

Monument number **678** has been replaced with a lead plug and tack with brass tag stamped "LS 1069"

Monuments numbered **583, 584, and 1066** have been replaced with a 5/8" x 24" iron rebar with Orange Plastic Cap stamped "HEA & Assoc"

These monuments have been replaced in their record recovery positions prior to construction activities and no analysis of the correctness of their location has been made.

Richard L. Bath, PLS 1069  
Director of Surveying  
Hardey Engineering & Assoc., Inc.  
PO Box 1625  
Medford, OR 97501  
Ph. 772-6880  
Fax 772-9573

(File: 381-25-00-MonReplacement.nar)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Richard L. Bath*

OREGON  
JULY 30, 1976  
RICHARD L. BATH  
No. 1069

RENEWS 12/31/05

