

SURVEY NO.__ 19430

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

PREPARED FOR: Buntin Construction LLC.

172 Parsons Drive, Suite 100 Medford, Oregon 97501

NEATHAMER SURVEYING, INC. PREPARED BY:

3132 State Street, Suite 110 P.O. Box 1574

Medford, Oregon 97501

LOCATION:

Located in the Southeast One-Quarter of Section 23 and the Northeast One-Quarter of Section 26, Township 37 South, Range 2 West of the Willamette Meridian, in the City of Medford, Jackson County, Oregon.

PURPOSE OF SURVEY:

Pursuant to Clients instructions, perform a field survey, prepare and process a Property Line Adjustment application with the City of Medford Planning Department, monument the resultant boundary corners and file a Map of Survey with Jackson County, Oregon.

SURVEY PROCEDURE:


Utilizing a Nikon DTM-522 Total Station and a Trimble Robotic Total Station with a TSCe and a TSC2 Data Collector with Trimble software, and Trimble 5700 RTK receivers and said TSCe and TSC2 data collectors, all found monuments, were tied in a closed traverse or by redundant ties.

Based on said traverse ties, Survey Number 9157, as filed in the office of the Jackson County Surveyor, Partition Plat recorded as Partition Plat Number P-42-2004 of the Records of Jackson County, Oregon, filed as Survey Number 18334 in the Office of the Jackson County Surveyor, Documents Numbered 94-32408, 05-38191 and 05-16178 of the Official Records of Jackson County, Oregon, and the Property Line Adjustments approved by the City of Medford Planning Department recorded as Documents Numbered 06-31523, 06-31524, 06-57944 and 06-57944 of the Official Records of Jackson County, Oregon, the resultant boundaries were monumented as depicted hereon.

BASIS OF BEARINGS:

Geodetic North based on the WGS 84 Datum, established by Global Basis of Bearings: Positioning System Observations. Bearing applied to found monuments, as depicted on the accompanying map.

REGISTERED **PROFESSIONAL** AND SURVEYOR OREGON SAN MILES RENEWAL: DEC. 31, 2006



Date: November 27, 2006

Jackson County Official Records 2007-008485

\$5.00 \$5.00 \$11.00

Cnt=1 Stn=4 SHAWBJ 02/20/2007 02:17:24 PM



Kathleen S. Beckett - County Clerk

AFFIDAVIT OF CORRECTION Pursuant to O.R.S. 209.255

19430

Be it hereby noted that on Survey Number 19430 in the office of the Jackson County Surveyor, a drafting error was made affecting the distance along the centerline of Ross Lane North. Said centerline distance from the ESE corner of DLC 72 position north to the intersection of the southerly boundary on the project reads 1853.17 feet. This distance should read 1583.17 feet.

Date: February 5, 2007 REGISTERED PROFESSIONAL OREGON RENEWAL: DEC. 31, ZOCK

STATE OF OREGON County of Jackson

ZNd , 2007, personally appeared the above Before me on named Logan Miles, a Registered Professional Land Surveyor, and acknowledged the foregoing instrument to be his voluntary act and deed.



I, Roger R. Roberts, Jackson County Surveyor, do hereby certify that I have examined this Affidavit of Correction and that the changes are permitted in accordance with Chapter 209, Paragraph 255, Oregon Revised Statutes.

February 20, 2007

