

SURVEY NARRATIVE

TO COMPLY WITH PARAGRAPH 209.250, OREGON REVISED STATUTES

DATE OF SURVEY:


August 15, 2016

SURVEYED BY:

Terrasurvey, Inc. 274 Fourth Street Ashland, Oregon 97520

SURVEY FOR:

Kogap Enterprises, Inc. P.O. Box 1608 Medford, Oregon 97501



LOCATION:

Located in the Northeast and Southeast Quarters of Section 31, Township 37 South, Range 1 West of the Willamette Meridian, in the City of Medford, Jackson County, Oregon.

PURPOSE:

To survey and monument that property line adjustment / lot consolidation as approved by the City of Medford in planning file No. PLA-16-074.

BASIS OF BEARINGS:

Basis of Bearing is the monumented center line of Meyers Lane per filed survey number 21452 as noted on the accompanying plat.

PROCEDURE:

Utilizing a Topcon total station, a Trimble S6 robotic total station and reflecting prisms, I tie and set the monuments as show. The center line of Meyers lane was held as the basis of bearing between the found monuments as show and the right of way per Instrument No. 75-03626 of the Official Records of Jackson County, Oregon was calculated to this line. The center line of Stewart Avenue was held between the City of Medford brass cap at the intersection of Meyers Lane and Stewart Avenue and the Northeast corner of Donation Land Claim No. 45 and the north boundary of the subject tract is calculated per Instrument Nos.97-45264 and 95-04268 of said Official Records. Existing monuments along the southwesterly line of the railroad right of way were tied with good conformance to record and accepted for the northeasterly boundary of the subject tract. The monuments set per filed survey number 9627 were tied and fit reasonable well with the exception of those monuments noted on the plat as PK nails set in concrete monuments. The current owners of both the adjoining tracts were questioned as to the origin of these monuments and were unsure as to who or when these two monuments were established.

These PK's were set in 6" PVC pipes with concrete filled centers as noted on the plat. They appeared to be of some age as there is significant lichen growth on the exposed surface of the concrete. As their origin could not be verified and they exceeded an acceptable positional value, I calculate record positions and note the differences on the plat. Monuments found for the southerly line of Tract 5 being the same as the southerly line of that tract described in Instrument No.2008-020900 of said Official Records were held and distance intersections were used to re-establish the points between. The southwest corner of said tract was established using the record distance north along the easterly right of way line of Myers Lane from the point of tangent at the south end along the east right of way as described in said Instrument No. 75-03626 of said Official Records.

PROFESSIONAL LAND SURVEYOR

and A

OREGON JULY 12, 2005 FRED A. FRANTZ No. 50077

Renewal 12-31-17