

Survey No.

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

SURVEYED FOR: BRYCE TAYLOR

1657 OLD STAGE ROAD

CENTRAL POINT, OREGON 97502

STEVE DAY

1658 OLD STAGE ROAD

CENTRAL POINT, OREGON 97502

SURVEYED BY: STEPHAN BAROTT LAND SURVEYING

1446 ST. ANDREW WAY MEDFORD, OREGON 97504 This Survey Consist Of:

Sheet(s) Map

page(s) Narrative

JACKSON COUNTY
SURVEYOR

LOCATION: Township 37 South, Range 2 West, Northwest quarter of Section 21 in Donation Land Claim No. 40, Willamette Meridian, Jackson County, Oregon. (Jackson County Tax Records 372W21B 3200, 3300, 3400 and 372W21 8900).

BASIS OF BEARING: Grid, Oregon Coordinate Reference System (OCRS) Grants Pass-Ashland Zone, per O.A.R. 734-005-0015.

PURPOSE: The purpose of this survey is to adjust tax lot lines for four tax lots as approved in Staff Report outlined in Jackson County Development Services File No. **439-21-00012-SUB**.

Parent Deed for Tax Lot 3200 as follows:

2020-043779 dated November 19, 2020

Parent Deed for Tax Lot 3300 as follows:

2020-045357 dated November 25, 2020

Parent Deed for Tax Lot 3400 as follows:

2020-043822 dated November 19, 2020

Parent Deed for Tax Lot 8900as follows:

2020-039904 dated October 26, 2020

PROCEDURE: Prior to commencement of this survey, deed records, surveys of record, and the staff report were reviewed.

For the most part, Real Time GPS (RTK) was utilized to control nearly all found corner points, utilizing the Oregon Department of Transportation's Geodetic Network (ORGN). Geodetic positions are on file with this office.

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

Monuments set are 5/8-inch by 24 or 30-inch iron pins with 1 ¾-inch diameter green plastic "Morasse-style" caps attached. Miscellaneous control point are either ½-inch diameter by 15-inch long iron pin with plastic cap, 3-inch long Survey Mark stainless steel nails and stainless steel washer stamped "BAROTT-SBLS LS 2332," or 5-inch long stainless steel cotton gin spindles.

HISTORY OF SURVEYS: The history of surveys of T.37 S., R.2 W. pertaining to this survey is as follows:

1854- Ives & Hyde, U.S. Deputy Surveyors, surveyed the Township and sub-divisional lines. Refer to Contract No. 39 dated January 4, 1854.

1855- 1874- The John F. Miller Donation Land Claim (DLC) No. 40 and the Robert Armstrong Donation Land Claim (DLC) No. 42 were surveyed by Sewell Truax in 1855.

The official patent No. 1863 for DLC 40 dated August 19, 1874, was signed by Ulysses S. Grant to Zerilda and John F. Miller.

The official patent No. 846 for DLC 42 dated May 24, 1867, was signed by Andrew Johnson to Minerva Jane and Robert C. Armstrong.

• SW Corner DLC No. 42- See Jackson County Re-establishment notes (DLC42SW GCDB 842100) December 11, 2015. (OR330370S0020W0_DLC42SW)

1908- L. Niedermeyer and wife created the L. and N. Subdivision No. 1 consisting of twenty-five (25) Lots in portions of Donation Land Claim No. 40 and 42, Section 16, 20, and 21, Township 37 South, Range 2 West, Willamette Meridian, Jackson County, Oregon on March 27, 1908. This survey created or documented public ways now known as Old Stage Road and Wendt Drive. This current survey is located in portions of Lots 19, 20, and 21 of said Subdivision. Refer to Subdivision Plat 003-116-A as filed in Jackson County, Oregon.

1963- Mark E. Boyden, PLS 281 surveyed a portion of Lots 19, 20, and 21 of the L. and N. SUBDIVISION NO. 1 and DLC #40, Section 21, Township 37 South, Range 2 West, Willamette Meridian, Jackson County Oregon, for Chester Wendt.

During this survey, Boyden discovered a ten (10) foot error between the South boundary of Wendt Drive and the North line of the Subdivision Lots 19-23. This survey identified as what is known today as 372W21B-3200, 3300, 3400 and 372W21-8900.

It has been assumed for many years that the South line of the 10-foot strip identified by Boyden marks the south line of the public access for Wendt Drive. Several of the Boyden monuments were found as shown on the Property Line Adjustment Map, page 1.

Refer to C.S. 2174 dated April, 1963.

1963- L.N. Dow, LS 251 retraced a portion of the Boyden survey C.S. 2174 and established the boundary of the current Tax Lot 372w21B-3400 for C.H. Sigman. During this survey, Dow did not

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

find or recognize the ten (10) foot gap along the North boundary of Lots 19-21 and the South right-of-way for Wendt Drive. Dow also established a thirty (30) foot private road close to the existing private drive as shown on the Property Line Adjustment Map, page 1. The issue is, the existing private drive was not constructed in the center of the Dow private road location. That easement is adjusted as shown.

Several of the Dow monuments were found by this survey, or by the current owner at one point in time.

Refer to C.S. 2232 dated July 16, 1963.

1967- C. Lind McBeth, LS 565 surveyed a parcel adjacent to and North of Wendt Drive. Several of the monument established during this McBeth Survey were recovered by this office during a previous survey. McBeth note the ten (10) foot discrepancy along the South line of Wendt Drive. Refer to C.S. 3445 dated April 1967.

1984- Verlyn Thomas, LS505 surveyed a parcel of land to the East of my client parcel for Dale Niedermeyer. Thomas found the SW corner for DLC No.42 and Wendt Drive, but failed to recognize the said ten (10) foot discrepancy along the South line of Wendt Drive as discovered by Surveyor Boyden during C.S. 2174.

Refer to C.S. 10117 dated September 1984.

2020- Stephan L. Barott, LS 2332 (this office) conducted a Property Line Adjustment (PLA) for Tax Lots 372W21B 3200, 3300, and 3400. During this PLA, I found or established the majority of the controlling corners for this current survey.

Refer to C.S. 23199 dated November 19, 2020.

No other surveys of record that pertain to this current project were found.

MONUMENTS ACCEPTED FOR CONTROL

1. SW CORNER DONATION LAND CLAIM NO. 42 (GCDB 842100), I found a 3-inch diameter brass cap monument, 1 foot deep.

From which:

Second reestablishment

- A 5/8-inch diameter iron pin, no cap, bears N.76°03'31" E., 10.25 FT. (C.S. record N.76°28'22" W., 10.24 feet)
- A 5/8-inch diameter iron pin, no cap, bears N.79°58'02" W., 12.65 FT. (C.S. record N.80°07'55" W., 12.54 feet)

Third reestablishment

• A 5/8-inch diameter iron pin with 2-inch dimeter aluminum cap marked

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

"JACKSON COUNTY SURVEYOR" bears S.89°37'11" W, 82.70 FT. (C.S. record S.89°34'10" E., 82.79 feet)

• The Northwest reference established in 2015 is gone.

ADDITIONAL MONUMENTS ACCEPTED FOR CONTROL OR ESTABLISHED ARE AS DESCRIBED IN C.S. 23199 AND AS SHOWN ON THE PROPERTY LINE ADJUSTMENT MAP, PAGE 1, WERE FOUND OR SET BY THIS OFFICE IN 2020.

GEODETIC POSITIONS FOR CERTAIN CORNER POINTS AS NOTED ON THE MAP OF SURVEY ARE AS FOLLOWS:

Utilizing the Oregon Department of Transportation's Oregon Geodetic Reference Network (ORGN), a network adjusted solution was computed for all stations (Real Time Kinematic, or RTK). Coordinates are NAD83(2011) Epoch 2010.00. Elevations are NAVD88 utilizing Geoid 12A Ellipsoid model. All surveyed points for this project were converted to the Oregon Coordinate Reference System (OCRS), Grant Pass-Ashland Zone as defined in Oregon Administrative Rules (O.A.R.) 734-05-0015, in International Feet.

 ${\sf GPS}$ #400 - FOUND 3-INCH DIAMETER BRASS CAP MONUMENT (SOUTHWEST DLC 42) DOWN 12 INCHES, MARKED:

T37S R2W
DLC
SW
42
C.S.
1980

LATITUDE

42°20'24.67706" NORTH

LONGITUDE

122°57'08.10686" WEST

ELEVATION

1459.07 FEET

Reference C.S. 2174, C.S. 23199, COUNTY RE-ESTABLISHEMENT NOTES OR330370S0020W0_DLC42SW (GCDB 842100) PAGES 1-3 DATED DECEMBER 11, 2015.

GPS #450- FOUND 5/8-INCH DIAMETER IRON PIN - DOWN 6 INCHES AND ON THE SOUTH EDGE OF A SMALL IRRIGATION DITCH.

LATITUDE

42°20'03.90502 NORTH

LONGITUDE

122°57'03.96219" WEST

ELEVATION

1440.38 FEET

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

Reference C.S. 2174

GPS #453 - FOUND 5/8-INCH DIAMETER IRON PIN.

LATITUDE

42°20'16.07821" NORTH

LONGITUDE

122°56'54.98971" WEST

ELEVATION

1425.15 FEET

Reference C.S. 2174

GPS #451 – SET 1/2-INCH X 15-INCH LONG IRON PIN WITH 1" DIAMETER PURPLE PLASTIC CAP MARKED:

SBLS GPS

CONTROL

LATITUDE

42°20'04.03676" NORTH

LONGITUDE

122°56'48.75390" WEST

ELEVATION

1423.77 FEET

FROM WHICH, THE CALCULATED SOUTHEAST TL 8900 PROPERTY CORNER (POINT FALLS IN AN IRRIGATION DITCH) BEARS SOUTH 55°27'01" EAST, 24.86 FEET.

Reference C.S. 2174

GPS #452 – SET 1/2-INCH X 15-INCH LONG IRON PIN WITH 1" DIAMETER PURPLE PLASTIC CAP MARKED:

SBLS GPS

CONTROL

LATITUDE

42°20'16.18557" NORTH

LONGITUDE

122°56'48.61461" WEST

Survey Narrative to Comply with Oregon Revised Statutes, Paragraph 209.250

ELEVATION

1416.14 FEET

FROM WHICH, THE CALCULATED NORTHEAST TL 8900 PROPERTY CORNER (POINT FALLS IN AN IRRIGATION DITCH) BEARS NORTH 41°01'40" EAST, 17.42 FEET.

Reference C.S. 2174

EQUIPMENT:

Equipment utilized throughout this survey includes a Leica TCRP-1203 Electronic Total Station and Leica GS14 GNSS RTK GPS Receiver adjusted utilizing Oregon Department of Transportation (ODOT ORGN) GPS network, NAD83(2011) EPOCH 2010.00. Elevations are NAVD88 using Geoid 12A. Additional Geodetic Positions are on file with this office.

REGISTERED PROFESSIONAL LAND SURVEYOR

Stephan Barutt

OREGON JULY 26, 1988 STEPHAN L. BAROTT 2332

RENEWS: DECEMBER 31, 202

DATE OF SURVEY: OCTOBER 4, 2021