

Butte Falls, Oregon
January 7, 1970

Dear Sir;

Please record following in Public Land Surveys

Section 2 Township 34 South Range 2 East Willamette Meridian

Narrative; To replace bearing trees destroyed in logging operation

Found; Rebar and aluminum cap, two down bearing trees N.E. corner section 2

Scribed; CC1 RS461 BT 8" W. fir S44°E 33.5'

CC2 RS461 BT 10" W. fir S85°W 30.7'

$\frac{35}{271}$ $\frac{T33S}{T34S}$

