



PROPERTY SURVEY
 SITUATE IN
 SE 1/4 SEC 20 T 36 S R 3 W WM
 JACKSON COUNTY OREGON
 G W PLUMB LAND SURVEYOR
 MEDFORD OREGON 28 DEC 1973

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
G. W. Plumb
 OREGON
 JULY 12, 1968
 G. W. PLUMB
 862

JACKSON COUNTY
 RECEIVED
 DEC 31 1973
 SURVEYOR

BEARINGS FROM RS 3988
 ● FND 5/8" IRON ROD
 ○ SET 5/8" X 24" IRON ROD
 SCALE 1" = 100'

Survey for Bob W. Erner
 530 Hodson Road
 Gold Hill, Oregon 97525

Survey by G. W. Plumb
 P. O. Box 904
 Medford, Oregon 97501

Location SE $\frac{1}{4}$ Sec. 20, T. 36S., R. 3 W., W.M., Jackson County, Oregon

Found 5/8" iron rods at the external corners of the north parcel shown on Registered Survey No. 4228. Set 5/82 x 24" iron rods to mark the corners of property described in Document No. 73-16041 of Official Records of Jackson County, Oregon. Reset 5/8" iron rod at the P. C. station on the right of way of Hodson Road.

28 December 1973

