



NORTH



MAP OF SURVEY  
 LOCATED IN  
 SE 1/4 OF NW 1/4, SW 1/4 OF NE 1/4, NW 1/4 OF SE 1/4  
 SEC. 20, TWP. 38S, R. 1 E.W.M.  
 JACKSON COUNTY OREGON

**MARY D. LYBRAND**  
 EVERETT L. SWAIN, R.L.S. ASHLAND, OREGON  
 NOVEMBER 19, 1973

SCALE: 1"=200'  
 BASIS OF BEARING: U.S.C. & G.S. TRUE BEARING N-S & SEC. 20



- FOUND MONUMENTS AS SHOWN
- SET 5/8 INCH IRON PIN WITH ALUMN. CAP

1/4 CORNER  
 FD. 5/8" I. PIN  
 Re: R/S No. 308B

SURVEY NO.

5507

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250  
OREGON REVISED STATUTES

SURVEY FOR: Mary D. Lybrand  
1350 Wilson Road  
Ashland, Oregon 97520

LOCATION: Situated in the Southeast quarter of the Northwest quarter, Southwest quarter of the Northeast quarter, Northwest quarter of the Southeast quarter of Section 20, Township 38 South, Range 1 East of the Willamette Base and Meridian, Jackson County, Oregon.

PURPOSE: To survey, monument and prepare a boundary line agreement and legal description for that parcel of land as shown on the accompanying map.

PROCEDURE: Commenced this survey in the vicinity of the quarter corner common to Sections 20 and 29, said Township and Range. After establishing the North-South centerline of Section 20, it was evident that a legal subdivision of said section was not economically feasible at this time. In reviewing F. Walker's field book, he had made a survey in Section 20 establishing the North and East boundaries of this parcel. However, the survey is questionable as to its legal status, in regards to the true interior sixteenth section lines. Therefore, the North and East boundaries were established by using the approximate location of the existing improvements and a boundary line agreement recommended to the client.

November 19, 1973

Everett L. Swain  
Professional Land Surveyor  
Ashland, Oregon

