

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Howard W. Terry

760 Twin Pine Circle Ashland, Oregon 97520

LOCATION:

Situated in Donation Land Claim No. 40, and the Southeast quarter of Section 5 and the Southwest quarter of Section 4, Township 39 South, Range 1 East of the Willamette Base and

Meridian, Jackson County, Oregon.

PURPOSE:

To survey and monument the parcels as shown on the accompanying

map per clients request.

PROCEDURE:

Commenced this survey by researching the Deeds of Record conveying Glenn Street. In 1908 Abel D. Helman deeded Glenn Street as shown in dashed lines. See Volume 67, Page 251 of the Deed Records of Jackson County, Oregon. In 1939 the City of Ashland Engineering Department, under the supervision of Frank Walker, City Engineer, proposed to realign Glenn Street as it was and is now traveled. The City of Ashland has a map showing the various proposals made at that time, on file in the office of the Engineering Department. However, no council acceptance of this proposal has been found to date.

Therefore, at the request of my client, I have used the alignment of Glenn Street per the City of Ashland's 1939 realignment. The realignment was designated as being 50 feet in width instead of the deed record 60 feet on said 1939 map. Utilizing the 50 foot right of way, leaves the corner of one building questionable as to encroachment into said right of way. If 60 feet is used there will be a considerable encroachment of a building or buildings The client has been made aware of these into the right of way. conditions.

Also, it was discovered that when retracing lot 3, block 13 of the Official City of Ashland Map accepted and adopted on Nov. 5, 1888 by the city council, the existing fence lines are consistently in error by 10 to 12 feet. It appears as though Glenn Street was probably established 50 feet in width many years ago and that all properties were then surveyed the record distances as shown on said 1888 map. The reduction in the right of way of Glenn Street from the deed width of 60 feet to 50 feet, could account for the consistent error in the existing fences Northerly of Glenn Street.

On April 18, 1975 street legalization and monumentation was discussed with the city attorney. He was very reluctant to pursue this course of action and indicated that as far as he was concerned the city had no problem. In any event it was felt that council action would be necessary to clear the problem. Following the aforementioned wishes of my client, I proceeded to

survey the parcels as shown on the accompanying map.

REGISTERED POFESSIONAL MEYOR JULY a. 1966

RECEIVED APR30 1975 SURVEYOR