HOFFBUHR SURVEYING INC., MEDFORD, OREGON

FEBRUARY 22, 1980


BASIS OF BEARING: VALLEY CENTER SUBDIVISION •____SET 5/8"x 24" I.PIN WITH CAP MARKED "LS 1640"

MINOR LAND PARTITION

LOCATED IN BLOCK 5 OF VALLEY CENTER SUBDIVISION AND N.E. 1/4 OF SEC. 14, T37S, R2W., W.M. CITY OF MEDFORD, JACKSON COUNTY, OREGON

FOR

JOSEPH M. MARKOVICH



8293

SURVEY NO.

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Joseph Markovich

3410 North Pacific Hwy. Medford, Oregon 97501

LOCATION:

Block 5 of Valley Center Subdivision and Northeast one-quarter (1/4) of Section 14, Township 37 South, Range 2 West, Willamette Meridian, Jackson County,

Oregon

PURPOSE:


To locate and monument the exterior boundary and

divide into 3 parcels

PROCEDURE:

The centerline of Mace Road was established using the monument found at the intersection of Mace and Elliott and the control established for Survey No. 5737. The South boundary of Lots 1, 2 and a portion of Lot 3 of Valley Center Subdivision was held between the pipe found at the Northwest corner of Lot 6 and the pipe found in the highway right of way. The positions of the Southeast and Southwest corners of Lot 2 were then determined on this line at record distances from the Northwest corner of Lot 6. From this location of the Southeast corner of Lot 2, the East line of Lot 2 was determined by holding the position of the capped pipe found in the Mace Road right of way, with the Northeast corner falling at the intersection of this line with the Mace Road right of way line. The Northwest corner of Lot 2 was located at a proportionate distance between the Northeast corner of Lot 2 and the Northwest corner of Lot 1. The rectangular portion at the Southwest corner of Lot 3 was located by record calls from the South and West boundaries of Lot 3. The North and South boundaries of the tract described in Volume 277/252 were determined by the pipes found at the Northeast and Southeast corners of the tract and the lines toward the corresponding pipes found in the highway right of way. The monumentation found from Survey No. 5737 was held as found, having been disturbed by fence construction.

February 25, 1980



372W 14AR

Hoffbuhr Surveying, Inc.