

Survey No. 9259 Page 1 of 1

ADDENDUM

Robert C. Jenkins Survey for:

83933 Cloud Nine Road Florence, Oregon 97439

Location:

Sections 24,25,35,36, Township 38S., Range 1E., W.M. Section 31, Township 38S., Range 2E., W.M. Section 6, Township 38S., Range 2E., W.M.

Purpose:

To note for the record that this survey has been corrected by Survey No. 9372.

* * RECEIVED * * Date 9/10/82 By SK This survey Consists of: O sheet(s) Map ____page(s) #e-ciee MERSON CO.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON July 9, 1965 RUSSELL D. HENDRICKS 688

CORNERS ACCEPTED FOR CONTROL

Controlling corners are described on the accompanying survey map, except those noted on Survey No. 9159 which are described as follows:

NE corner Section 6, T.39S., R.2E.,W.M.; found 2" iron pipe with brass cap exposed 6" by Survey No. 4719.
References from which:
A 10" W. Oak bears S61°31'05" E 214.10', scribing visible
A 14" W. Oak bears N07°02'05"W 165.35', scribing visible
Fence Corner N30°E 2.00'.

West & Corner Section 6, T.39S., R.2E., W.M.; Found 1" iron pipe with brass cap by 1967 county Re-estab.

References from which:
A 12" W. Oak bears N7720E 42.2'
A 15" W. Oak bears S0020W 72.6'
A 7" W. Oak bears N870W 25.0'

Trees live, faces healed.

SW corner Section 36, T.38S., R.1E., W.M.; Found 1" iron pipe inside 2" iron pipe by 1953 county re-estab.

References from which:
A 5" W. Oak bears N522 E 96.7', face healed
An 8" Ash bears Sh82 E 51.0', scribing visible.
An 8" W. Oak bears SO62 W 59.8', face healed.

Trees live.

West a corner Section 35, T.38S., R.1E., W.M.; Founf 1" iron pipe with brass cap by Survey No. 7035.
References from which:
A 14" W. Oak bears N67% E 177.7', scribing visible, tree live.

North & corner Section 35, T.38S., R.1E., W.M.; Found 1" iron pipe with brass cap by 1977 county re-estab.

References from which:
A 6" W. Oak bears N72 35'E 97.10', scribing visible.
An 8" W. Oak bears S27 55'E 48.24', scribing visible.

Trees live.

SE corner Section 24, T.38S., R.1E., W.M.; Found 1" iron pipe with brass cap by 1969 county re-estab.

References from which:
A 13" W. Oak bears N18½ E 48.0'
A 7" W. Oak bears SOO½ W 17.9'
An 8" Yellow pine bears S45½ W 28.4'
Trees live, faces healed.

West corner Section 24, T.38S., R.1E., W.M.; Found 1" iron pipe with brass cap by 1974 county re-estab.

References from which:
An 8" W. Oak bears N1120 E 30.20'
An 8" B. Oak bears N420 W 13.40'

Trees live, scribing visible

* * RECEIVED * *

Date 4/13/82 Byss
This survey Consists of:
_____ sheet(s) Map
____ page(s) Narrative

JACKSON COUNTY

SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

Rusull Oblandust

OREGON July 9, 1965 RUSSELL D. HENDRICKS 688

SURVEY NARRATIVE TO COMPLY WITH OREGON REVISED STATUTES 209.250

SURVEY FOR:

Robert C. Jenkins 83933 Cloud 9 Rd. Florence, Oregon 97439

LOCATION:

Sections 24,25,35,36, T.38S., R.1E., W.M. Section 31, T.38S., R.2E., W.M. Section 6, T.39S., R.2E., W.M.

BASIS OF

BEARINGS:

 \mathbb{W}_4 corner Section 6 to SE corner Section 24 using original North bearing.

PURPOSE:

1. To monument property corners.

2. To correct County Survey File Number 9159 due to a new controlling corner found after recordation.

PROCEDURE:

Searches for information included City of Ashland (Jim Roberts), the BLM, Jackson County Surveyor's Office, and Joseph Dauenhauer (adjacent landowner). Initial retracement consisted of a closed traverse using known monuments. A field search for original G.L.O. corners was made using retracement data, original notes, and county search records. To set desired corners, several lost controlling corners were first located by proportional measurements. All corner location was done by the Bureau of Land Management's Manual of Surveying Instructions. Original topographic line calls were checked and found to be close enough to substantiate the proportioned corners as established by this survey.

The Jackson County Surveyor's Office was asked to search for several original corners thought to be lost by this survey. After Survey No. 9159 was recorded, the 4 corner between Section 25 and 30 was remonumented by the county using notes from a 1952 unrecorded survey by Lovejoy for C. Dunham. This necessitated the correction of Survey No. 9159. The monuments set in Survey No. 9159 now become references to the true corners. The true corners will be monumented with brass caps by August, 1982, when weather allows vehicular access to supply materials.

The SE and NW corners of Section 25 have been searched for by the county using this survey's retracement. No definitive original evidence was found.

The Southeast corner of Township 38 South, Rnage 1 East has been located by double proportioned measurements. A field search provided no original evidence, most likely because of ground disturbance in the area. The two nearby fence corners were considered as possible evidence of the original corner. Because of the erratic nature of these fences and the fact that two fence corners are in this area, neither was accepted as valid monuments. Original topographic calls fit the proportioned corner location reasonably well.