, **y**.

MINOR LAND PARTITION

File 82-61-MP

Located in Sec.28, T.36S., R.IW., W.M., Jackson Co., Oregan February 1963

SURVEYOR'S CERTIFICATE					RECORDER'S CERTIFICATE				
I, Verlyn Thomas, a duly Registered Land Surveyor of State of Oregon, hereby certify that this map correctly represents a survey made by me or under my direction, and complies with the regulations for "Minor Land Pertitions." PROFESSIONAL PR				.Fi led fi in Volu	Filed for record this day of		Land Partitions" in Jackson County, Oregon. Kettler & Breatt County Clerk		
APPROVALS Approved by the Jackson County Department of Planning & Development. by date 4/183 All taxes, fees, assessments or other charges as required by O.R.S. 311.280	RECOURVEY PROMASE TO SO S	NO.	3					S89°59'30"W 1643.00 1/4 Q1r. (per R.S. 1013) 28	
have been paid as of May 9 , 1983. You Stewart / Here Here Level Director of Assessment & Taxation	EXTENSION	3/4" i. pin	327.II	N 89* 5 9'	05" E 325.00		325.00	3/4" I. pin	
David Hopkins 3900 Pico Drive Central Point, Oregon ** RECEIVED ** Drug 5/U/B3 0/SK And the Contract of the	SUBDIVISION 724.04	724.235	PARCEL 3 5.414 ocres	725.06	PARCEL 2 5.413 acres	725. 91	PARCEL I 5.419 acres	6.75 Y 735.48 Scale: I = 100,	
Soils information for this property indicate a high ground-water ponding hazard which may require special design standards to overcome. This property, at the time of final plat recording, was not shown to be suitable for development—and will require at a minimum, provision of sewage disposal facilities prior to issuance of building or mobile home set-up permits by the Jackson County Department of Planning and Development.	LOTUS N 0° 1 8' 39" V		SEE	S 0° 03'04" E	SURVEY	S 0° 03'03"E	N O. 1013	LEGEND 5/8"x24" I. pin w/cap stamped LS 505 set Monument found BASIS OF BEARINGS: Survey No. 1152	
The above statements placed upon this plat as a condition of approval by the Jackson County Department of Planning and Development.		5/8" I. pin	323.83 C	OREY (19K	325.00 S 89°52' E S89°54'E)	ROAD	325.00 	3/4" I. pin 1/2" I. pipe (I. l. de	
This is to correly that this fracing is an anext copy or the original plat. **Landard Surveyor*** **Landard Surveyor*** **Landard Surveyor*** **Landard Surveyor** **Landar	Mc1 AUG	DRIV							

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

For:

David Hopkins 6900 Pico Drive Central Point, Oregon

Purpose:

To survey and monument a Minor Land Partition according to approved preliminary plat submitted by client.

Procedure:

The parent parcel had been surveyed and monumented by J.H. Clabby by a survey dated July, 1956, for Bud Hoover. LOTUS SUBDIVISION EXTENSION NO. 3, which is adjacent to the westerly boundary and a portion of the northerly boundary of the parent tract was also surveyed by J.H. Clabby in August, 1956, for the Hoovers. It is interesting to note that the bearing of the north line of Section 28 is shown on the plat of LOTUS SUBDIVISION as South 89° 59' 30" East, and on Survey No. 1013 as North 89° 59' 30" West. Yet the narrative for Survey No. 1013 states "the north line of Section 28 bears South 89° 59' 30" West", which is then parallel with the bearing as shown on Survey No. 1013 for the north line of the parent tract.

It appears that this error in bearing on the plat of Survey No. 1013 carried over to the plat of said LOTUS SUBDIVISION EXTENSION NO. 3.

This error notwithstanding, the parent parcel had been surveyed and monumented at the same time as said LOTUS SUBDIVISION EXTENSION NO. 3, and the monuments should control.

The exception to this is the location accepted for Corey Road. It is not indicated on Survey No. 1013 what Clabby used to determine the location of Corey Road.

This section of road was surveyed and monumented on the 1910 road survey (Sta. 685+58.8 to Sta. 698+68.8). A check with the County Department of Public Works indicated this to be the only location data they had of record, and to accept this location, as had been previously indicated on Survey No. 1152. The 1/2" pipes set in 1910 for the abovementioned Stations were recovered and accepted as the centerline for this section of Corey Road. The monuments from Survey No. 1013 were accepted for side-line control only.

The three parcel were then monumented as shown on the accompanying plat.

* * RECEIVED * *

Date 5/11/83 By5K__
This servey Coldists of:

Line 10 Marrative

John 10 0081174

SURVETOR

PROFESSIONAL LANDSURVEY R LANDSURVEY R MAY 13. 1960

36-1W-28