

83-22099

2:39

400
200

STATE OF OREGON)
)ss
County of Jackson)

AFFIDAVIT OF CORRECTION

I, Verlyn Thomas, a duly Registered Professional Land Surveyor of the State of Oregon, being first duly sworn, do hereby depose and state that I surveyed the tract of land shown on the map filed in Volume 5 at page 152 of "Minor Partitions" in the Office of the County Clerk, Jackson County, Oregon, also filed in the Office of the Jackson County, Oregon, Surveyor's Office as Survey No. 9801, and that the following corrections are required, to-wit:

1. That certain corner identified as the N.W. Corner of D.L.C. 39 should be identified as the N.W. Corner of D.L.C. 76.
2. The reference in the title block identifying the Partition location as the N.E. 1/4 Sec. 26, T.37S., R.2W., W.M. is incorrect, and should read the N.W. 1/4 Sec. 26.

Partitioner-Owner: Robert Sevcik


Verlyn Thomas
 Registered Professional Land Surveyor
 #505
 304 South Holly
 Medford, Oregon 97501

Subscribed and sworn to before me this 22 day of December, 1983.

My Commission Expires: 6-30-85 Valarie J. Gibson
 Notary Public for Oregon

Examined and approved this 22 day of December, 1983.

Edward J. [Signature]
 Jackson County Surveyor



Jackson County, Oregon
 Recorded
 OFFICIAL RECORDS
 2:39 DEC 22 1983 P.M.
 KATHLEEN S. BECKETT
 CLERK and RECORDER
 By: Ruby A. [Signature] Deputy

83-22099

2:39

400
200

STATE OF OREGON)
)ss
County of Jackson)

AFFIDAVIT OF CORRECTION

I, Verlyn Thomas, a duly Registered Professional Land Surveyor of the State of Oregon, being first duly sworn, do hereby depose and state that I surveyed the tract of land shown on the map filed in Volume 5 at page 152 of "Minor Partitions" in the Office of the County Clerk, Jackson County, Oregon, also filed in the Office of the Jackson County, Oregon, Surveyor's Office as Survey No. 9801, and that the following corrections are required, to-wit:

- 1. That certain corner identified as the N.W. Corner of D.L.C. 39 should be identified as the N.W. Corner of D.L.C. 76,
- 2. The reference in the title block identifying the Partition location as the N.E. 1/4 Sec. 26, T.37S., R.2W., W.M. is incorrect, and should read the N.W. 1/4 Sec. 26.

Partitioner-Owner: Robert Sevcik

Verlyn Thomas
 Registered Professional Land Surveyor
 #505
 304 South Holly
 Medford, Oregon 97501

Subscribed and sworn to before me this 22 day of December, 1983.

My Commission Expires: 6-30-85 Valarie J. Gibson
 Notary Public for Oregon

Examined and approved this 22 day of December, 1983.

Edward G. M. Smith
 Jackson County Surveyor

Valarie J. Gibson
 VALARIE J. GIBSON
 NOTARY PUBLIC - OREGON
 My Commission Expires 6-30-85

Jackson County, Oregon
 Recorded
 OFFICIAL RECORDS
 2:39 DEC 22 1983 P.M.
 KATHLEEN S. BECKETT
 CLERK and RECORDER
 By Ruby A. Poling Deputy