



D.L.C. 47

D.L.C. 46

E. Line D.L.C. 46

Hamlin (175-605)

E. Line D.L.C. 47  
W. Line D.L.C. 46

Corn (346-64)

(S 89° 54' E 440.35')  
(East 440.35')

Harry & David (341-494)

Corn (346-64)

Harry & David (341-494)

Note:

Rec. Desc. thus (East 440.35')

(N 89° 54' 00" W 440.35')

(N 89° 54' 00" W 468.75')

Pinnacle Packing Co. (223-592)

Scale 1" = 100'



REGISTERED  
**OREGON**  
LAND SURVEYOR

NOVEMBER 18, 1948

BOUNDARY SURVEY  
D.L.C. 46, T.38S, R.1W, W.M.  
JACKSON COUNTY OREGON

Survey Narrative to Comply with Section 87-330

1947 Oregon State Laws

Survey for: Wayne Stine  
 Medford, Oregon

Purpose of Survey: To locate property boundaries.

Survey Location: D.L.C. 46, Township 38 South, Range 1 West,  
 Willamette Meridian, Jackson County, Oregon.

Survey Procedure: Located Northeast and Northwest corners  
 D.L.C. 46, also Northeast corner D.L.C. 47,  
 all in Township 38 South, Range 1 West,  
 Willamette Meridian. Survey procedure as  
 shown on map. Set 1" iron pipe at property  
 corners.

Leland P. Lovejoy, Registered Land Surveyor.

Work completed July 29, 1951.

