



**LEGEND:**

- ⊙ = FOUND CORNER OF GOVERNMENT SURVEY (RE-ESTAB'D)
- ✱ = FOUND 5/8" IRON PIN WITH ALUM. CAP MARKED O.S.H.D. R./W.
- = FD. 5/8" IRON PIN WITH PLASTIC CAP MARKED SWAIN RLS 759
- ✱ = FOUND 5/8" IRON PIN WITH PLASTIC CAP MARKED THOMAS PLS 505
- = SET 5/8" I. PIN WITH PLASTIC CAP MKD. FRIAR PLS 961

BASIS OF BEARINGS: THE N.-S. CENTERLINE OF SECTION 14 AS SHOWN ON SURVEY NO. 9668

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Larry J. Friar*  
OREGON  
JULY 16, 1971  
LARRY J. FRIAR  
961

\*\* RECEIVED \*\*  
Date: 5/2/86 By: SK  
This survey consists of:  
1. Survey Map  
1. Field Notes  
1. Plat  
1. Instrument

SURVEY NO. 9668  
39 IE 14A T.L. 3100

**MAP OF SURVEY  
FOR  
SUPER 8 MOTELS**

9  
LOCATED IN THE N. W. 1/4 OF SECTION 14, T. 31 S.,  
R. 1 E., W.M. JACKSON CO., OREGON  
SCALE: 1" = 50' DATE: APRIL, 1986  
SURVEY BY: FRIAR - MOFFIT & ASSOCIATES  
MEDFORD OREGON

Survey No. 10549

Survey Narrative to comply with O.R.S. 209.250

Survey For: Super 8 Motels  
c/o Peninsula Development, Inc.  
P.O. Box 3825  
Lacey, WA 98503

Location: N.W. one-quarter Section 14, Township  
39 South, Range 1 East, Willamette Meridian,  
Jackson County, Oregon.

Purpose: To determine the boundaries of parcel  
shown on annexed map.

Procedure: Located and made ties to property corners  
established by previous surveys, their posi-  
tions are noted relative to record position  
where they differ.

The South right-of-way of Greensprings  
Highway was determined from Survey No's.  
7699 and 7614. The existing right-of-way  
pins have apparently been disturbed or were  
erroneously set.

The subdivisional lines of the N.W. one-  
quarter of Section 14 have been previously  
checked during other surveys by this office.

Date: April 14, 1986

Larry J. Friar  
Friar-Moffit & Assoc.  
717 W. 10th St.  
Medford, OR 97501

