MARK E. BOYDEN RPLS ORE 281 108 MISTLETOE ST., MEDFORD, OREGON 97501 PHONE (503) 773-6000

GARY D. KAISER RPLS ORE 803

SURVEY NO.

10804

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

SURVEY FOR:

Medford Gun Club

1259 East Vilas Road

Medford, Oregon

SURVEY BY:

Boyden Surveyors 108 Mistletoe St. Medford, Oregon

LOCATION:

SE 1/4 of Section 31, T36SRlW,W.M.

BASIS OF BEARINGS:

South boundary of Section 31 per filed

No. 2050

DATE:

Commenced October 23, 1984 Completed Febuary 18, 1987

ORIGINAL PUPPOSE:

To monument and descibe the West 400 feet of the South-half of the SE 1/4 of Section 31, T36SRIW lying North from the North right-of-way line of East Vilas Road, for

proposed lease purposes.

FINAL PURPOSE:

To set monuments as shown, without describing a particular proposed lease parcel.

PROCEDURE:

Utilizing a one-second Theodolite and E.D.M. equipment, the desired tract was monumented from found controlling monumentation as shown on the annexed map.

Monuments marking the previous proportioned positions for the North and South Quarter corners of Section 31 have been obliterated as well as their nearby references.

Proportioned these positions from existing Section corners found as shown, referencing same as follows:

At the Quarter corner common to Section 30 and 31, set a 3/4" x 36" galv. iron pipe 30" in the ground with a 2" br. cap marked:

T36S RlW

 $1/4 \frac{s}{s} \frac{30}{31}$

RLS 803 1984 From which:

Center of a railroad tie corner post (fences West and Northeasterly) bears South 89 1/2° West, 22.3 feet.

Center of a railraod tie corner post (fences North and Southwesterly) bears North 23° East, 14.0 feet.

At the Quarter corner common to Section 31, T36SRlW and Section 6, T37SRlW set a 3/4" x 36" galv. iron pipe flush with the pavement surface of East Vilas Road with a 2" br. cap marked:

T36SR1W

 $1/4 \frac{s}{s} \frac{31}{6}$

T37S RLS 803 1984

From which:

A 5/8" x 24" rebar with plastic cap bears North 0° 15' 43" West, 30.0 feet.

The center of a sanitary sewer manhole lid bears North 64 1/2° East, 37.0 feet.

A subdivision of Section 31 was computed and the position of the North boundary of the South-half of the SE 1/4 was found to agree with 5/8" iron pin monuments set on Filed Survey No. 2050 within reasonable limits. This boundary was accepted as found to be monumented.

The existing fence near the West boundary of the subject tract is located near the East right-of-way line of vacated P & E railroad. This is approx. 25 feet East of the North-South center line of Section 31. The adjoining property owner to the West and the client were aware of this. A line of stakes was set on the North-South center line for proposed fence relocation purposes. Said fence line has now been constructed between monuments as set on this survey.

It should be noted that the original Deed of Conveyance for the railroad right-of-way (Deed Vol. 59, Page 534) contained a reversionary clause.

The recording of the Deed of Abandonment and Relinquishment by Medford Corporation of said railroad right-of-way (Deed Vol. 562, Page 418) would appear to vest said abandoned railroad right-of-way in this Quarter-Quarter Section back to the Medford Gun Club.

FEBRUARY 18, 1987

REGISTERED PROFESSIONAL LAND SURVEYOR

Yan D. Karon

OREGON JULY 16, 1967 GARY D. KAISER No. 803