


S.W. CORNER
KENDALL ADDN.
FD. 1" IRON PIN
6" DEEP

- LEGEND:
- = FOUND 5/8" IRON PIN
 - = SET 5/8" IRON PIN MKD. FRIAR PLS 961
 - ⊙ = FOUND MONUMENT AS NOTED.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Larry J. Friar

OREGON
JULY 18, 1971
LARRY J. FRIAR
961



MAP OF SURVEY
FOR
THE SALVATION ARMY

LOCATED IN THE E 1/2 OF SEC. 24, T. 37S., R. 2W.,
W. M., JACKSON CO., OREGON.

SCALE: 1" = 40' DATE: JULY 1988
BASIS OF BEARING: EASTERLY LINE OF CENTRAL AVE.
PER SURVEY NO. 5471
SURVEYED BY: L. J. FRIAR & ASSOCIATES, MEDFORD, OR.

Survey No. **11344**

Survey Narrative to comply with O.R.S. 209.250

Survey for: The Salvation Army
304 Beatty Street
Medford, Oregon 97501

Location: East 1/2 Section 24, T. 37 S., R. 2 W.,
W.M., Jackson County, Oregon

Purpose: To monument corners of several parcels of
land acquired by the Salvation Army.

Procedure: All of the existing corner monuments that
could be located were tied in by a closed
traverse, their relationship calculated and
shown on the attached map.

Filed Survey Nos. 7150 and 8828 developed a
procedure for determining the property line
locations of adjacent properties and was
accepted as the best solution by this
surveyor.

The ambiguities caused in the location of
property lines in this area by the over-
lapping of previous subdivisions, i.e. Beatty
Addition, Cottage Addition and Wildwood
Addition, of which no original monumentation
was found, can only be rectified by boundary
line agreements which have been recommended
to the Clients.

Date: August, 1988

Larry J. Friar
L.J. Friar & Associates
717 W. 10th, Suite 1
Medford, Oregon 97501

T37S, R2W, Section 24

