

		1169
Survey	No.	1100

Survey Narrative to comply with O.R.S. 209-205 and O.R.S. 209-120

Survey for: Mr. Henry Sandvig

Survey by: Edward A. McGinty, 10/30/58

BASIS OF BEARING: Solar observation

PRECEDENCE OF SURVEY:

Determined the center line of Beall Lane from monuments found along the center line of Beall Lane. At the intersection of Hanley Read, a 3/4 inch iron pin, and at the intersection of Grant Road, a 1/2 inch iron pipe, a stone at the northeast corner of DLC 44 and $1\frac{1}{2}$ inch iron pipe at the southwest corner of DLC 54, being both in T37S, R2W. Center line of Grant Road determined from a 5/8 inch iron pin along the westerly boundary of the road and the easterly boundary of Grant Acres Sub-division. Traversed a line parallel too and 13 feet from the center of the creek, a proposed boundary line. From deeds of record and instuctions of client, surveyed parcels as shown.

MCKSON MOKSON MOVED 1958 CUUNIY REGISTERED
OREGON
LAND SURVEYOR

EDITARD A. MCGINIY