

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

Jackson Hot Springs

Page 2

BASIS OF BEARING:

True Meridian at the N-S Centerline of Section 31, as derived from the National Oceanic and Atmospheric Administration (formerly Coast and Geodetic Survey) survey net established in 1968 and filed in the office of the Jackson County Surveyor.

May 21, 1990

ref: AF1266T.NAR

Swain Surveying, Inc. 27 1/2 North Main Street Ashland, Oregon 97520

Tax Lot 1600, 38-1E-31

REGISTERED PROFESSIONAL AND SURVEYOR OREGON
JULY 8, 1968
EVERETT L SWAIN

* * RECEIVED * *

Date 5-23-90 By 5k

This survey Consists of

___ sheet(s) Map

2 page(s) Narrative JACKSON COUNTY SURVEYOR



27½ North Main Street Ashland, Oregon 97520

Survey No. 12047

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

JACKSON HOT SPRINGS 2253 Highway 99 N Ashland, Oregon 97520

LOCATION:

Situated in Southeast Quarter and the Northeast Quarter of Section 31, Township 38 South, Range 1 East of the Willamette Base and Meridian, Jackson County, Oregon.

PURPOSE:

To survey and monument the boundary line between Tax Lot 1400 and 1600, Assessor's Map 38-1E-31. Also, description of clients ownership was furnished by the clients representative.

PROCEDURE:

Commenced this survey from control previously established in the course of executing Recorded Survey No. 7020 for Herbert Lewis. A great deal of investigation was made while surveying the property of Herbert Lewis. The monument shown at circle 'A', on the accompany map, was found while conducting a search for additional monumentation per this survey. origin is also unknown. The Deeds of Record in this general vicinity are very difficult to retrace. also appears that some of these deeds may have been prepared by someone other than a Surveyor. After much consideration of the facts, as revealed by the various deeds, it was suggested to the client that they consider giving Tax Lot 1400 all their deed record front footage along the relocated Highway 99 N right of way and thereby eliminate a possible controversy about the deficiencies that show up in the retraced distances, along said right of way line of Highway 99, compared to those distances called for in the Deeds of Record. My client has the Senior Title and should receive what their record calls for; However, some of the found monumentation would suggest a different location than where record would place these lines. Therefore, utilizing the Deed Record call of the intersection of the right of way lines of the OLD HIGHWAY 99 AND THE relocated HIGHWAY 99, the deed record distance of 310.0 feet, for Tax Lot 1400, was utilized to establish the boundary line between said The retracement distance between Tax Lot 1400 and 1600 is slightly greater than that of deed record and the retracement distance along the OLD HIGHWAY 99 right of way line is slightly greater than that of deed record. My client has therefore protected the deed record values of Tax Lot 1400 rather than protecting the distance values of their own property, as the information on the accompanying map will show. There is presently an Asphaltic Surface parking area encroaching on Tax Lot 1600 and was apparently placed there by parties of Tax Lot 1400. This is yet to be resolved by the parties of both Tax Lots. remainder of the survey is as shown on the accompanying