

DARREL W. EDWARDS OREGON REG. 741 ARIZONA REG. 9746



REGISTERED LAND SURVEYORS 823 WEST 8TH ST. MEDFORD, OREGON 97501 (503) 776-2313 • (503) 471-7059 DAVID A. EDWARDS OREGON REG. 2339

A boundary line agreement was attempted with the adjoiners to the South with no success. In the interest of closing a sale on Parcel 2 of this plat it was decided to record the plat as is and pursue the boundary line agreement when cooler heads could prevail. Monuments set on this survey consist of 5/8" x 24" steel pins with red plastic caps mkd. "D.A. EDWARDS-LS 2339".

BASIS OF BEARINGS: R.S.N. 8024 via existing control established by this office on R.S.N. 11741.

EQUIPMENT:

Nikon NTD-4 Semi-automatic theodolite/E.D.M.

DATE

COMPLETED:

August 13, 1991

* * RECEIVED * * Date 8-20-91 By & This survey Consists of: 1 sheet(s) Map 2 page(s) Narrative JACKSON COUNTY SURVEYOR

REGISTERED PROFESSIONA LAND SURVEYOR **EDWARDS** 2339

Edwards Surveying & Land Planning Inc.

DARREL W. EDWARDS OREGON REG. 741 ARIZONA REG. 9746



DAVID A. EDWARDS OREGON REG. 2339

REGISTERED LAND SURVEYORS 823 WEST 8TH ST. MEDFORD, OREGON 97501 (503) 776-2313 • (503) 471-7059

SURVEY NUMBER

12627

SURVEY NARRATIVE TO COMPLY WITH CHAPTER 209, PARAGRAPH 250, OREGON REVISED STATUTES

SURVEY FOR:

Neal A. Hughes

2366 Silver Palm Drive

Medford, Oregon

LOCATION:

In the NW 1/4 of Section 15, T. 34 S.,

R. 1 W., W.M., City of Shady Cove, Jackson

County, Oregon.

PURPOSE:

To locate and monument the boundaries of that tract having for it's South line the North line of tract desc. in Vol.271, Pg. 595 and for it's Northerly boundary the South line of tract desc. in Vol. 592, Pg. 302, and to partition said tract into 3 new parcels as shown on the

accompanying plat.

PROCEDURE:

Utilizing existing control points and data established by this office during the execution of R.S.N. 11741 and 11848, as well as data found in the above noted deeds, computed the boundaries of the subject tract. Much difficulty was encountered in locating the brass pipe called for in the latter deed noted above. This was because said pipe falls some 24 feet Southerly from the deed position. The monument is as described in the deed, however, and was therefore held for NE/SW position. The South line of the subject tract also presented extreme difficulties. The original deed which segregated the property lying South of the South line of the subject tract, (Vol. 271, Pg. 595), calls for an iron pin at a point 241 feet Northerly along the Easterly R/W line of Hwy. 62 as it's NW corner. After much searching both North and South of the computed position it was decided that this pin had been lost. The deed then calls for a bearing of "East 296 feet more or less, in line with a post set in cement" to an iron pin on the West bank of the Rogue River". None of these monuments could be recovered. In Vol. 399, Pg. 411 a bearing of North 85° 57' East is called for this line. Although using this bearing would fit the improvements better, the grantor in that deed had no right in my opinion to sell land lying North of the "East" line first called for. Even using this latter bearing would not eliminate substantial encroachments.