
Survey For GEORGE WATSON Located in Sec. 36, T.37 S.R.2 W., W. M. July 1959.

Fd. i. pin over......

being a è P.I.

J.C.D.R. Vol. 48, Pge. 570.

& the S.W. cor.



1327.6'...

. 80.0

S. 89° 54' W.

STEWART

Survey Narrative to Comply With Paragraph 209.250 Oregon Revised Statutes

FOR: George Watson

PURPOSE: To monument and describe three (3) parcels on the West side of Chestnut Avenue, being located in Section 36, Township 37 South, Range 2 West.

PROCEDURE:

A previous survey had monumented Chestnut Avenue and several parcels on the West side of Chestnut Avenue.

After tying in several of the monuments of said previous survey, it was determined that:

- 1. The previous survey had not located the true centerline of Stewart Avenue (being approximately 4 feet in error at the West line of Chestnut Avenue).
- 2. The true bearing of Chestnut Avenue after using a mean of the monuments found on said previous survey is North 0° 05' 40" East instead of "North".

Because of these survey errors, it was decided to let the boundaries remain according to the original survey, but re-describe them as to their true location.

Monumented and described the parcels as shown on the attached map.

July 1959



OREGON LAND SURVEYOR

MARK E. BOYDEN