

Page 2 of 2 sheets



MARK E. BOYDEN
R.P.L.S. ORE. 281

108 MISTLETOE ST., MEDFORD, OREGON 97501
PHONE (503) 773-6000

13730

said Filed Survey No. 13670 for the positioning of the North and South property boundaries. The boundary line agreements described in Instrument No 82-06777 and Instrument No. 82-06692 were apparently not monumented. From said data, monumented the desired corners at positions shown on the annexed map.

* * RECEIVED * *

Date 11-15-93 By BC

This survey Consists of:

____ sheel(s) Map

2 page(s) Narrative
JACKSON COUNTY

SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON NOV. 9. 1951 MARK E. BOYDEN 281

ExpIRES: 12/31/93.

MARK E. BOYDEN R.P.L.S. ORE. 281

108 MISTLETOE ST., MEDFORD, OREGON 97501

PHONE (503) 773-6000

survey no. 13730

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

Oregon Department of Transportation SURVEY FOR:

R/W Section

1299 NW Ellan Street Roseburg, OR 97470

BOYDEN SURVEYORS SHRVEY BY:

> 108 Mistletoe Street Medford, Oregon 97501

LOCATION:

SW 1/4, Section 13, T. 37 S. R. 2 W., WM City of Medford

Jackson County, Oregon

BASIS OF BEARINGS:

Filed Survey No. 13670

DATE:

November 8, 1993.

PURPOSE:

1. To monument the corners of tract described as Parcel 2 in Instrument No. 76-07238, Official

Records.

2. Prepare resultant description for Parcel 2 and prepare a consolidated description for Parcel 1 of Instrument No. 76-07238, Official Records and for Tax Lot 3700, 37 2W 13 CB.

PROCEDURE:

Utilizing EDM equipment, tied to the Southwest corner of Donation Land Claim No. 60, monuments along the East boundary of the Northerly parcel monumented on Filed Survey No. 6841, monuments along the West boundary of Filed Survey No. 4732, monuments on the South boundary of Filed Survey No. 13670, and the Brass cap in concrete set by the County Surveyor for the Southwest corner of Donation Land Claim No. 59.

The 3/4" iron pin set in concrete as reported by the County Surveyor in 1940 and references for the Northeast corner of Donation Land Claim No. 88 have been obliterated by Industrial construction according to the County Surveyor's Department. This is indeed unfortunate, as all the deeds in the Southerly portion of HOWARD PARK SUBDIVISION, an unrecorded subdivision, are tied to this Claim

corner. The road deed for Berrydale Avenue (Volume 161 Deeds, Page 96) commences at said Northeast corner of D.L.C. 88 and runs East 2.72 chains to the West boundary of D.L.C. 60; thence runs North, 600 feet to the point of beginning. A survey for Owen Oregon Lumber Co. (now Medite Co.) was performed by my father, C. Z. Boyden in 1924 and a copy of the map of survey was filed in the County Deed Records in Volume 157 Deeds, Pages 341-343. This survey map indicates said obliterated Claim corner was North 0° 01' East 811.4 feet and North 89° 55' West, 179.0 feet from the Southwest corner of D.L.C. 60. The monument set on said Lumber Co. survey from the Southwest corner of D.L.C. 60, North 0° 01' East, 1411.4 feet has apparently been destroyed or disturbed by utilities construction.

Ties to monuments set on Filed Survey No. 13670 from the West line of D.L.C. 60 and the North boundary of Berrydale Avenue fit amazingly close and were utilized for control on this survey. Monuments found set on Filed Survey No. 2154 and Filed Survey No. 6841 are relatively close to