

## Page 2

I interviewed Mr. Kenneth L. Nichols, who at one time owned tax lot 1200 and 1600. I visited the site with Mr. Nichols and he indicated the road exists today as it did when he acquired the land. He also indicated the road centerline was to be the boundary between tax lots 1200 and 1500. I the boundary between tax lots 1200 and within also interviewed several other landowners within also interviewed several other landowners within the area and each indicated the existing roadway to be the only route used as access.

My clients ownership extends to the centerline of the road and there is no disagreement in the location of the road as it existed at the time tax lot 1500 was created and the present location. I monumented the boundaries of tax lot 1500 as shown on the attached map. At the request of the neighbors using the road as access I did not disturb the rock surface to the extent necessary to set iron post monuments, instead I set 6 inch long rail spikes 4-6 inches below the road surface.

SURVEY:

September 10, 1994

SURVEYOR:

HAROLD L. CENTER
Registered Professional Land Surveyor
Oregon Certificate No. 1071 (12/31/95)
2604 David Lane
Medford, Or. 97504

(ref:LW:Robinson,03)

\*\* RECEIVED \*\*

Date 9-28-94 By & OR E G O N

This survey Consists of:

| \_\_\_\_\_stratic\_Liap
| 2 \_\_\_\_por-(striberrative) | JACKSON COUNTY | SURVEYOR

## PAGE 1

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Mr. David R. Robinson

P. O. Box 800

Talent, Or. 97540

LOCATION:

S.E.1/4 Section 30, Township 38 South, Range 1

West, Willamette Meridian, Jackson County,

Oregon. (tax lot no. 1500)

BASIS OF BEARING:

Record Survey No. 6767, bearings based on

recovered monumental established by that

survey.

PURPOSE:

To monument the boundary of tax lot no. 1500, 381W30, as shown on the attached survey map and

to post the north, south and west lines.

PROCEDURE:

I began this survey with the recovery of my survey control established during Record survey No. 13721. From this control I performed a closed traverse around the perimeter of tax lot

1500 tying controlling monuments established by Surveyor J. A. Hoffbuhr, Reference Record Survey

No. 6065 to this traverse.

The east boundary of tax lot 1500 is described "along the center line of a presently existing roadway". The west boundary of tax lot 1200 is described by course and distance form the Center 1/4 corner and does not reference the road. Surveyor R.L. Bath located a portion of the west boundary of tax lot 1200 (reference R.S. 6767). Due to the lack of reference to the road within the description a hiatus is created between the two parcels. The strip apparently

remains with tax lot 1600.