

Edwards Surveying & Land Planning Inc.

816 West 8th Street Medford, OR 97501 Tel.: (503) 776-2313 FAX: (503) 776-9978



SURVEYING • ENGINEERING • PLANNING

223 SW "I" Street Grants Pass, OR 97526 Tel.: (503) 471-7059 FAX: (503) 471-7809

14243

Set 5/8" x 24" steel pin CS 1/16 corner:

w/yellow plastic cap.

14" D. Fir bears S. 79° E. 24.00' Scribed "CS 1/16 S 6 BT" From which:

14" Madrone bears N. 40 W. 44.80'

Scribed "CS 1/16 S 6 BT"

Set 5/8" x 24" steel pin E 1/16 corner:

w/yellow plastic cap.

10" Madrone bears N. 70° W. 2.50' From which:

Scribed "E 1/16 S 6 BT" 7" Madrone bears S. 55° W. 14.90'

Scribed "E 1/16 S 7 BT"

SE 1/16 corner: Set 5/8" x 24" steel pin

w/yellow plastic cap.

From which: Metal fence post bears N. 540 W.

5.20'

Metal fence post bears N. 34° E.

4.50'

BASIS OF BEARINGS: N-S center line of Section 5, per

County Survey No. 10898

Nikon NTD-4 Semi-automatic Theodolite/E.D.M.

DATE COMPLETED: October 19, 1994

* * RECEIVED * * Date 10-24-94 By BF This survey Consists of: \perp sheet(s) Map JACKSON COUNTY SURVEYOR

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Darrel W. Edward

DARREL W. EDWARDS

Expires 12/31/95

Edwards Surveying & Land Planning Inc.

816 West 8th Street Medford, OR 97501 Tel.: (503) 776-2313 FAX: (503) 776-9978



223 SW "I" Street Grants Pass, OR 97526 Tel.: (503) 471-7059 FAX: (503) 471-7809

SURVEYING • ENGINEERING • PLANNING

14243

SURVEY NARRATIVE TO COMPLY WITH CHAPTER 209, PARAGRAPH 205, OREGON REVISED STATUTES

Boise Cascade Timber & Wood Products Group SURVEY FOR:

P.O. Box 100

Medford, Or. 97501

Southwest 1/4 of Section 5 and the South 1/2 LOCATION:

of Section 6, Township 35 South, Range 2 West of the Willamette Meridian in Jackson County,

Oregon.

To survey between found survey markers set in PURPOSE:

County Survey No. 3857 and 10898 and post and blaze lines as shown on the accompanying MAP

OF SURVEY.

To survey, post and blaze lines in Section 6 as

shown on the accompanying MAP OF SURVEY,

Ran a closed traverse beginning at the 1/4PROCEDURE:

corner between Sections 5 and 6; thence Northerly to a control nail in Section 31 (Tied to the North 1/4 corner of Section 6); thence traversed Southwesterly to the West 1/4 corner of Section 6; thence along the East-West center

line to the approximate Center 1/4 Corner; thence Southerly to the South 1/4 corner of Section 6; Returned to the approximate Center South 1/16 corner and traversed East to the approximate Southeast 1/16 corner; thence South to the approximate East 1/16 corner between Section 6 and 7; thence East to the Section corner common to Sections 5, 6, 7 and 8; thence East to the West 1/16 corner between Sections 5 and 8; thence North to the Southwest 1/16 corner; thence East to the Center South 1/16 corner; thence North to the Center 1/4 corner;

thence West to the 1/4 corner, the point of beginning.

Set 5/8" x 24" steel pin Center 1/4 corner: w/yellow plastic cap.

5/8" x 24" witness pin w/plastic From which: cap stamped "D.W. EDWARDS LS 741"

bears:

N. 45° E. 15.33'

S. 45° E. 16.83' S. 45° W. 16.86' N. 45° W. 19.43'