
T. L. NO. 7400-38-IW-25CB



DECLARATION


know all men by these presents that we, Robert A. Guth miller and Peggy A. Guthmitter, husband and wife, are the ewaers in fee simple as tenants by the entirety of the lead described in the annexed Surveyor's Certificate, subject to a trust deed executed by us in favor of Seattle-First Metional Bank, a National Banking Association, as beneficiary, dated November 6,1995, and recorded November 14,1995, as Document No. 95-32533 of the Official Records of Jackson County, Oregon, and that we have caused the partitioning as shown hereon.

Robert A. Guthmiller

Jeggy A. Guthmiller
Deggy A. Guthmiller

STATE OF OREGON S.S.

apple 27,1998 A.D. 1998 Personally appeared the above named Robert A. Guthmiller and Peggy A. Guthmiller, husband and wife, and acknowledged the foregoing instrument to be their voluntary act and deed before me:



Notary Public for Oregon

FOR AFFIDAVIT OF CONSENT to the above Declaration by Seattle-First National Bank, the beneficiary of the trust deed recorded as Document No. 95-32533 of the Official Records of Jackson County, Oregon, See Document No. 98- $\frac{29550}{29550}$ of said Official Records.

SURVEYOR'S CERTIFICATE

I, George R. Burrell, a duly Registered Professional Land Surveyor of the State of Oregon, hereby certify that this plat correctly represents a properly monumented survey made by me, and the following is a correct description for the tract herein partitioned:

Commencing at the Southeast corner of Donation Land Claim No. 68, Township 38 South, Range I West of the Willamette Meridian, Jackson County, Gregon; thence North 2027.39 feet; thence West 329.44 feet to the Southeast corner of Lot 1, Block I of MEADOW SLOPE SUBDIVISION, for the initial Point of Beginning; thence North 22°08'49"East (record North 22°30'East) along the Southeasterly boundary of said Subdivision, 268.54 feet to the Southwesterly right of way of Old Pacific Highway No. 99 (now Talent Avenue); thence along said right of way, South 46°25' 10"East 124.96 feet; thence leaving said right of way, South 24°09'53"West 265.24 feet; thence North 46°19'31" West (deed record North 46°10'31"West) and parallel to the Southwesterly right of way of Old Pacific Highway No.99 according to Meadow Stope Subdivision, 115.00 feet to the Initial Point of Beginning. April 27,1998

* * RECEIVED * *

Date 6-30-98 By 65

This survey Consists of:

L sheet(s) Map

L page(s) Narrative

JACKSON COUNTY
SURVEYOR

PROFESSIONAL
LAND SURVEYOR

Burell

OREGON

JULY 10, 1964

GEORGE R. BURRELL

638

Exp. 12/31/99

All taxes, fees, asressments or other charges as required by O.R.S. 92.095 have been

Jackson County Tay Sollector

Jeffyn Dagety _____

6/29/98 Date

Filed for record this 30 day of June 1998 at 10:08 0'clock A M. and recorded as PARTITION PLAT NO. P-46-1998 of the Piat Records of Jackson County Oregon.

Index Volume 9 at Page 46

KAthleen S. Beckett

Spring Walker

SURVEY NARRATIVE TO COMPLY WITH O.R.S.209.250

FOR:

Robert Guthmiller 225 Lani Way Talent,Oregon 97540

LOCATION:

D.L.C. No. 68 in Section 25, Township 38 South, Range 1 West W.M. in the City of Talent, Oregon

PURPOSE:

To monument and plat a partition of T.L. No. 7400-38-1W-25CB as requested by the client and approved by the City of Talent Planning Department.

PROCEDURE:

The found centerline street monuments of Lani Way as established by Meadowbrook Estates Subdivision (R.S. No. 7345) and the found monuments of recorded Survey No. 5207 were held as control for establishing the parent tract according to Recorded Survey No. 5207 The monument at the S.W. corner of the parent tract (the Initial Point of this survey) was found to be undisturbed. monument of R.S. No. 5207 at the S.E. corner of the parent tract has been disturbed by adjacent concrete driveway construction. monument was set according to R.S. No. 5207 record as shown on said plat. The witness corner monument of R.S. No. 5207 at the N.E. corner of said tract has been disturbed slightly by concrete sidewalk construction. The variation being shown in the Legend on said plat. The 1" iron pipe witness corner at the N.W. corner of said tract (the N.E. corner of Lot 1, Block 1 of Meadow Slope Subdivision) has been destroyed by power pole replacement. A new witness corner monument was set as shown on the accompanying plat. The division boundary between parcels no. 1 and 2 was established according to the clients instructions and city approval.

