OREGON

LAND SURVEYOR

Survey No.

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250

CEC 9 1980 Cregon Revised Statutes

For: warvin williams

locate about one acre in the S.E. corner of his

Father's property, to be bound on the South by the North right of way of Valley View Road.

Procedure:

The Father's property was tied to the S.W. corner of D.L.C. No. 42 which I didnot find. From the county Road Department I got the survey made by the road department which gave a tie on the D.L.C. line to the center line of Valley View Road, some references off the center line which I found, and a station that had been established on centerline opposite the property line I wanted.

From the references I was able to restablish the tie on the D.L.C. line and then the centerline of the road, which I chained to a point opposite the S.E. corner of the property. I then turned the required angle to give me the bearing of the East line of the property and set the corner on the right of way, having first checked the existing fence for line, there being no corner to mark the N.E. corner of the whole area. I then continued North on the line from the road the distance designated by the owner, also turned the angle to give me the right of way of the road and measured the distance required. At this corner I turned an angle from the right of way to give me a line North parallel with the East line and measured the same distance as on the East line, from this point I turned to the N.E. corner previously set and turned the angle and chained the distance for a closeure.