



LEGEND

- SET 5/8" X 30" REBAR WITH PLASTIC CAP MARKED "TEMPLIN LS2359"
- FD. 5/8" IRON ROD 6" DEEP PER FS 1673
- ⊗ FD. 5/8" IRON ROD PER FS 6322
- FD. 1&1/2" IRON PIPE PER FS 6432, BENT EASTERLY
- ⊙ FD. 1/2" IRON ROD PER FS 6432
- ⊙ FD. 5/8" IRON ROD WITH PLASTIC CAP MARKED "HUCK" PER FS 13174
- ▲ FD. 5/8" IRON ROD WITH PLASTIC CAP MARKED "FRIAR" PER FS 16522
- FD. 5/8" IRON ROD PER FS 6446
- ⊙ FD. BRASS CAP MONUMENT 12" DEEP PER JACKSON COUNTY RE-ESTABLISHMENT
- △ INDICATES CALCULATED POSITION
- { } INDICATES RECORD DATA PER FS 13174
- { } INDICATES RECORD DATA PER FS 16522
- [] INDICATES RECORD DATA PER FS 6322
- (()) INDICATES RECORD DATA PER FS 6432
- [] INDICATES RECORD DATA PER FS 13174
- () INDICATES RECORD DATA PER FS 6446
- FS INDICATES FILED SURVEY

BASIS OF BEARING: PER FS 16522

**** RECEIVED ****
 Date 2-18-03 By [Signature]
 This survey consists of:
1 sheet(s) Map
0 page(s) Narrative
 JACKSON COUNTY
 SURVEYOR

SURVEY NARRATIVE

PURPOSE: To prepare a Property Line Adjustment map reflecting the approved tentative map by the City of Jacksonville.

PROCEDURE: The outside boundary of my client's property had been surveyed and marked by filed survey numbers 6446 and 6322. These monuments were found and tied together, along with monuments set on filed survey numbers 1673, 13174 and 16522. Utilizing deeds O.R. 74-10031, O.R. 87-19007, O.R. 89-30624, Vol. 567, Page 287, Vol. 566, Page 175 and Vol. 8, Page 696 and ties made from my control traverse I computed and set monuments along the newly adjusted boundaries.

[Signature]
 APPROVED BY JACKSONVILLE CITY PLANNING
 DATE 2/28/03

REGISTERED PROFESSIONAL LAND SURVEYOR
[Signature]
 RICHARD G. TEMPLIN
 2359
 MY CERTIFICATE EXPIRES JUNE 30, 2004

RICHARD TEMPLIN LAND SURVEYING
 P.O. BOX 1946 899-2032 JACKSONVILLE, OREGON
PROPERTY LINE ADJUSTMENT
 LOCATED IN
 A PORTION OF LOT 3, BLOCK 60, TOWN OF JACKSONVILLE
 IN THE SE 1/4 OF THE NE 1/4 OF SECTION 31 &
 THE SW 1/4 OF THE NW 1/4 OF SECTION 32
 T.37S., R.2W., W.M.
 CITY OF JACKSONVILLE, JACKSON COUNTY, OREGON
 DATE: FEBRUARY 18, 2003

For: Dr. Robert Miller
 640 S. Oregon Street
 Jacksonville, Oregon 97530