

九

LAND SURVEYING. LLC

This survey Consists of: sheet(s) Map page(c) Hamadvo JACKSON COUNTY SURVEYOR

> PROCEDURE (cont.): of said Section 17. At one time in history, the river may have occupied such area, but in recent history, the current position of the river in this locale lies within the Northwest Quarter of the Northwest Quarter of Section 17. The 1949 deeds for the parent tract of the adjacent property to the south and west of the subject property describe said Northwest Quarter of the Northwest Quarter of Section 17 in Volume 328, Page 13, excepting the north 120 feet and the west 1250 feet of said Northwest Quarter. Therefore I only extend the southeasterly line of the subject tract to the north line of the tract described in said Deed Record Volume 328, Page 13, thence run west to intersect the thread of the Applegate River.

> BASIS OF BEARING: The Basis of Bearing for this survey is the line between the South Quarter Corner and the West Quarter Corner of Section 8, Township 38 South, Range 4 West of the Willamette Meridian, having a record plat bearing of North 44°17'53" West, as referenced on Survey No. 7556, on file in the office of the Jackson County Surveyor.

DATE: August 10, 2011

PREPARED BY: Shawn Kampmann, **Professional Land Surveyor**

POLARIS LAND SURVEYING, LLC

S:\surveys\660-11\Perillo Survey Narrative.doc

P.O. Box 459

Ashland, Oregon 97520

(541) 482-5009

RENEWAL DATE: 6/30/13

SURVEY NO. 20928

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Leonard Perillo

15985 North Applegate Road Applegate, Oregon 97530

LOCATION:

The Southwest Quarter of Section 8, Township 38 South, Range 4 West,

Willamette Meridian, Jackson County, Oregon.

PURPOSE:

To survey and monument that tract of land described within Instrument

No. 99-57531 of the Official Records of Jackson County, Oregon.

PROCEDURE:

Utilizing an electronic Leica TCRP 1203 robotic Total Station with ranging prisms and a Leica 1200 Smart Station Global Positioning Satellite (GPS) survey grade receiver, in conjunction with survey control previously established by this office during the performance of Survey No. 20246, I locate and tie monuments recovered from Survey No. 7556, as well as U.S. Bureau of Land Management (BLM) and Jackson County Surveyor monuments located at the South, West and Center Quarter Corners and the Southwest Corner of Section 8 and the West Quarter Corner of Section 17, in order to determine the north, west and south deed lines of the subject property.

A survey error was found to exist along the south and southeasterly lines of the subject property on Partition Plat No. P-13-1991 and perpetuated by a Property Line Adjustment in Survey No. 14357 which indicates that the southeasterly property line intersects the thread of the Applegate River, thence runs northwesterly along said thread to the west line of Section 8. But although the parent tracts of the subject property make calls to the Applegate River in Deed Record Volume 367, Page 95, they do not include any area that lies south of Section 8 into Section 17, except parts lying within the Northeast Quarter of the Northwest Quarter