

#### **SURVEY NARRATIVE**


## TO COMPLY WITH PARAGRAPH 209.250, OREGON REVISED STATUTES

#### DATE OF SURVEY:

October 24, 2016

### **SURVEYED BY:**

Terrasurvey, Inc. 274 Fourth Street Ashland, Oregon 97520



## SURVEY FOR:

DDR Properties 4100 Newport Place #400 Newport Beach, Ca 92660

### LOCATION:

Located in all quarters of Section 18 and the Northwest and Southwest quarters of Section 19, Township 39 South, Range 2 East of the Willamette Meridian, Jackson County, Oregon.

## PURPOSE:

To survey and monument the South and West line of the East half of Lot12 and the North line of the West half of Lot 12 and to show the boundaries and easements of record as described in that title report prepared by First American Title Company, Order No. 7162-2715815 and dated October 6, 2016.

# BASIS OF BEARINGS:

Basis of bearing is between the brass caps monumenting the Northwest corner and the North quarter corner of Section 18 per filed survey 16292.

### PROCEDURE:

Controlling monuments per re-establishment notes as cited on the plat were tied for Section 18 and 19. No evidence was found for the Southwest corner of Section 18 or the West 1/4 corner of Section 18 or 19 or the South 1/4 corner Section 18. These corners were calculated by single proportion measurement as shown and none were monumented. Lotting for Section 18 was calculated per the original GLO 1855 plat of the Section. The northeast corner of Donation Land Claim 40 was searched for and not found. This corner was calculated holding the record distance tie from the original notes to the Southwest corner of Section 18 along the south line of Section 18 to the east line of DLC 40 and the distance call to the West quarter corner of Section 18 along the west line of Section 18 to the north line of DLC 40. A distance, distance intersection

from these two points, using the record distances along the DLC lines in Section 18, as called was calculated for said northeast corner. The Special 1865 plat showing the lotting of the abandoned Donation Land Claim No.39 was reviewed and it was determined that the lotting within the abandoned claim for Lot 12 was to the sectional subdivision lines. The area for said Lot 12 appears to in error as the areas of Lot 7 and Lot 12 do not add up to the area as shown on the original 1855 plat for the area of the southwest quarter of the northwest quarter. I hold the original area for Lot 7 and proportion the position for the south line of Lot 12 using the areas per the original plat. These methods result in the factor between the areas of Lot 7, 8 and 9 and the NW 1/4 of the NW 1/4, between record and this survey, agreeing to the hundredth. The center line of Emigrant Creek Road was tied at various positions and the description per Volume 188, Page 478 was calculated and the geometry when translated and rotated to the surveyed center line fit well with the road as surveyed, however the ties to the northwest section corner in the deed were disregarded as holding them would place the majority of the roadway outside the description. Monuments set per S/N 2306 were recovered for the southwest and southeast corners of that tract described in Inst. No.81-07873 and the record bearing and distances were rotated to the found monuments. It appears using this method that the location and alignment of Emigrant Creek Road has moved since the date of the original survey and the differences are as shown. Corners were set per the clients request as shown. The encumbrances per the title report supplied by the client are shown on sheet 2.

PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 2005
FRED A. FRANTZ
No. 50077

Renewal /2-31-17