-
$\stackrel{\smile}{}$
. 6/20/2019 12:30:20 PM. ARCI
-
á
2
ö
ä
Ξ
5
₹
2
3
ď
⋛
Š
ā
Ě
$\mathbf{z}$
2
3
a
ě
7
ŏ
Ž
₹
۶
o
<u>Nisi</u>
€
\$
S
ā
_
SS
2
٠
0
'n
×
35-02-17 Knapi
8
Š
3


## 22880 APPROVALS: MEDFORD CITY PLANNING I certify that, pursuant to authority granted in ordinance No. 5785 this plat is hereby approved. Re: LDS-18-123 Planning Director MEDFORD CITY ENGINEER AND SURVEYOR Examined and approved this ... DECLARATION \* \* \* KNOW ALL PERSONS BY THESE PRESENTS, that Ross Lane, LLC, an Oregon Limited Liability Company, Declarant, is the owner in fee simple of the land shown hereon and further described in the Surveyor's Certificate, and have caused the same to be subdivided and platted into lots and streets as set forth hereon, and the number of each lot, the size of each lot and the course and length of all lines are plainly set forth and that this plat is a correct representation of this subdivision. Declarant does hereby dedicate to the public, for public use, the streets shown hereon as Kaitlin Lane, and Heber Lane, and additional right of way along Maple Park Drive, and Ross Lane North, together with those areas designated hereon as public utility easements (PUE's), Charter Communications, their assigns and/or successors in interest are hereby granted the right to install and maintain television cable service over, across, and through the Public Utility Easements as shown hereon. Declarant does hereby grant to the City of Medford an easement on Lots 13 and 14, for their exclusive use as a fire and emergency vehicle turnaround (FDTE) as designated hereon. Declarant does hereby grant to the City of Medford a storm drain easement (SDE) on Lots 13 and 15, for their exclusive use as designated hereon. Declarant does hereby make and establish a 5' wide Private Storm Drainage Easement (PSDE) across Lots 1 thru 4, for the benefit of said lots, and a 5' wide Private Storm Drainage Easement (PSDE) across Lots 5 thru 12, for the benefit of said lots as shown on Sheet 2. Declarant does hereby deed to the City of Medford in fee, 1' Street Plug shown on Sheet 2 on the condition that the Street Plug at the South end of Heber Lane will automatically be dedicated to the public upon approval and acceptance of the extension of said street, by the City of Medford. Declarant does hereby designate this subdivision as ROSS LANE SUBDIVISION. IN WITNESS WHEREOF, I have set my hand and seal this 25th day of Tune 2019 fampy manin ROSS LANE, LLC By: RAY KNAPP, MANAGING MEMBER

Personally appeared before me the above named RAY KNAPP on behalf

of ROSS LANE, LLC and acknowledged the foregoing instrument to be

# **ROSS LANE SUBDIVISION**

CITY OF MEDFORD PLANNING ACTION LDS-18-123 **LOCATED IN** S.E. 1/4 OF SECTION 23, T37S, R2W, W.M. IN THE CITY OF MEDFORD JACKSON COUNTY, OREGON May 23, 2019




Filed for record this 6th day of August 2019,	at <u>2:13</u>
O'Clock, $P.M.$ , and recorded in Volume $45$ , of Plats at	
Pageof records of Jackson County, Oregon.	
Christing N. Walker Jones J. Mo	(gan)
County Clerk  APPROVED FOR RECORDING:	8/12/15
County Commissioner / Administrator	Date

## ASSESSOR / TAX COLLECTOR

_	as required by O.R.S.	92.100 this 6 day
of August		aslly Turm, agent
3		Assessor, Department of Assessment

All taxes, fees, assessments or other charges as required by O.R.S. 92.095 have been



### SURVEYOR'S CERTIFICATE

I, John L. Hardey, a duly Registered Land Surveyor of the State of Oregon, License No. 1990, do hereby certify that this plat correctly represents a survey made by me or under my direction, and that I have correctly surveyed and marked with proper monuments the tract of land hereon shown, and that said plat and survey conform with the ordinances of the City of Medford and the statutes of the State of Oregon, and that the following is an accurate survey and title description of said tract's exterior

All that real property described in Document Number 2015-030616 of the Official Records of Jackson County, Oregon, being in Donation Land Claim Number 72 (DLC 72) in the Southeast One-quarter of Section 23, Township 37 South, Range 2 West of the Willamette Meridian, City of Medford, Jackson County, Oregon, more particularly described as follows:

Commencing at the southeast corner of Donation Land Claim 73 (also being the northeast corner of said Donation Land Claim 72). Township 37 South, Range 2 West of the Willamette Meridian, Jackson County, Oregon; thence along the east line of said Claim, (and centerline of Ross Lane North) South 00°05'40" West, 344.40 feet (record 344.275 feet), to the centerline of Maple Park Drive to the west; thence continuing along the east line of said Claim and street

centerline, South 00°05'40" West, 103.27 feet; thence North 89°54'20" West, 30.00 feet to the west right of way line of Ross Lane North and a set 5/8" by 30" iron rebar, being the initial Point of Beginning; thence along the west right of way line of Ross Lane North, South 00°05'40" West, 109.91 feet to a set 5/8" by 30" iron rebar, said point being on the south line of that tract described in Document No. 2015-030616 of the Official Records of Jackson County, Oregon; thence along the aforementioned south line, South 89°32'20" West, 565.32 feet to a found 5/8" iron pin marked "Neathamer Surveying"; thence along the west line of the aforementioned tract, North 00°05'40" East, 187.76 feet (record 187.86 feet) to a found 5/8" iron rebar, said point being on the south right of way line of Maple Park Drive; thence east along the aforementioned south right of way line, North 89°32'20" East, 547.32 feet to a set 5/8" by 30" iron rebar, said point also being on a right of way line as described in Document No. 2008-025685 of the Official Records of Jackson County, Oregon; thence along said line, South 00°05'40" West, 2.20 feet to a set 5/8" by 30" iron rebar; thence continuing easterly along said line. South 89°54'20" East, 10.00 feet; thence continuing southeasterly along said line. South 25°46'19" East, 0.08 feet to a set 5/8" by 30" iron rebar; thence South 89°32'20" West, 165.95 feet to a set 5/8" by 30" iron rebar, and the beginning of a 20 foot radius curve to the left with a central angle of 87°50′50″; thence along said curve, 30.66 feet (long chord bears South 44°01'05" West, 27.75 feet) to a point of tangency and a set 5/8" by 30" iron rebar; thence along said west line. South 00°05'40" West, 25.71 feet to a set 5/8" by 30" iron rebar, and the beginning of a 72.5 foot radius curve to the lef with a central angle of 10°43'18"; thence along said west line, and the arc of said curve, 13.57 feet (long chord bears South 5°15'59" East, 13.55 feet) to a set 5/8" by 30" iron rebar, and the beginning of a 20 foot radius compound curve to the left with a central angle of 79°50'02"; thence along said west line, and the arc of said curve, 27.87 feet (long chord bears South 50°32'39" East, 25.67 feet) to a set 5/8" by 30" iron rebar; thence North 89°32'20" East, 172.05 feet to the initial Point of

AFFIDAVIT OF CONSENT

From FIRST AMERICAN TITLE, Trustee, for RSM REVOCABLE TRUST, recorded as Document

No. 2019-22736 . ORJCO.

#### **SURVEY NARRATIVE:**

STATE OF Oregon

his voluntary act and deed.

Notary Public for Oregon

CXD. 12/12/21

County of Jackson S.S.

PURPOSE: To survey, monument, and plat ROSS LANE SUBDIVISION, as approved by the City of Medford Planning Commission, per LDS-18-123.

OFFICIAL STAMP LORI ANN B!LLINGS

NOTARY PUBLIC-OREGON

COMMISSION NO. 969570

MY COMMISSION EXPIRES DECEMBER 12, 2021

PROCEDURE: The found monuments noted on the Plat were tied in using a Trimble 5600 Robotic unit via closed traverse and doubled side ties. The legal description for this property contained in JCOR 2015-030616 appears to be based on a recorded boundary survey by Neathamer Surveying, Inc., Recorded Survey 18647, recorded in 2005. The legal description did not call to any monuments other than the southeast corner of DLC 73. The survey was found to have error in a distance call for the width of a narrow strip of land along Maple Park Drive. This error affected the legal description for a tract of land excepted from the legal description contained in JCOR 2015-030616. The width of that strip of land is noted as 2.73 feet on RS 18647 but was intended to read 2.37 feet. It was also called as 2.73 feet in the deed. The distance discrepancy was discussed with and verified to be 2.37 feet by Neathamer Surveying, Inc. staff member Cael Neathamer in May and June of 2018. Found Neathamer monuments matched the intended dimension of 2.37 feet rather than 2.73 feet which is further verification that the above noted dimension of 2.73 feet is in error and the dimension of 2.37 feet is the proper dimension to be used for the deed. The above noted deed description JCOR 2015-030616 and Recorded Survey 18647 were used primarily as the basis of the plat boundary; except the bearings were rotated to fit the record bearing for Maple Park Drive Terrace Subdivision, Phase 1, established by RS 17589, and recorded on December 11, 2002, and also the dimension of 2.37 feet noted above instead of 2.73 feet was used to determine the boundary of this plat. Said description fit well with the other monuments found in the area including the centerline monuments for Maple Park Drive. The above noted deed description was checked against surrounding deed descriptions and surveys for any conflicting senior rights or overlaps. The centerline of Maple Park Drive was established using a best fit straight line at record bearing per RS 17589, through the found centerline monuments. The north line of the plat boundary was established by parallel offset of the aforementioned centerline. The east line of the plat boundary was established using a parallel offset from the DLC line between the southeast corner of DLC 73 and the southwest corner of DLC 88. These are new DLC monuments replacing those from 1970 and they fit well for line but appeared to be off slightly to the north from the record distances. The south line of the plat was established using a best fit straight line at record bearing through the found monuments along the south line and tying to the found monument by Neathamer Surveying, Inc. at the southwest corner. The west line was established using a best fit straight line at record bearing through existing monuments found along said west line set by both Neathamer Surveying, Inc. and L. J. Friar and Associates.

BEARING: Centerline of Maple Park Drive RS 17589

37 2W 23 DC of Tax Lot 1600

SHEET INDEX

SHEET 1 SIGNATURE SHEET SHEET 2 BOUNDARY DATA SHEET 3 DETAILS

I HEREBY DECLARE THAT THIS IS AN EXACT COPY OF THE ORIGINAL PLAT.

\* RECEIVED \* DATE 8/6/19 BY PB This survey consists of:

Sheet(s) Map

page(s) Narrative JACKSON COUNTY **SURVEYOR** 

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JULY 16, 1982 **JOHN HARDEY** 1990

RENEWS: 6-30-2019



HARDEY GROUP, INC

P.O. BOX 1625 MEDFORD, OREGON 97501-0063 VOICE: 541-772-6880 EMAIL: info@hardeygroup.com

SHEET 1 OF 3

#### **ROSS LANE SUBDIVISION** CITY OF MEDFORD PLANNING ACTION I HEREBY DECLARE THAT THIS IS AN LDS-18-123 EXACT COPY OF THE ORIGINAL PLAT. LOCATED IN S.E. 1/4 OF SECTION 23, T37S, R2W, W.M. IN THE CITY OF MEDFORD JACKSON COUNTY, OREGON May 23, 2019 BASIS OF BEARING = CENTERLINE OF MAPLE PARK DRIVE (RS 17589) 5 10 FND 2½" BRASS CAP FLUSH WITH PAYEMENT MARKED CENTER OF NEW BRASS CAP MAPLE PARK TERRACE SUB - PH I APPEARS TO BE NORTH O.13' FROM THE PRIOR 1970 DLC NE I 72 60"M 34. 344.275 55 CAP, RECORD POSITION 22 2 2017 LEGEND: MAPLE PARK DRIVE ★ SET %" X 24" IRON REBAR W 1½" ALUMINUM CAP MARKED "HARDEY GROUP" 127.50' (127.51' R.S. 17589) N89° 32' 20"E N89° 32' 20"E N89° 32' 20"E 317.55' (317.50' - RS 17589) - BASIS OF BEARING 150.27' (150.31 RS 17589) FOUND BRASS CAP MAPLE PARK DRIVE 127.54 86.90' ADDITIONAL 2.37' RIGHT OF WAY 230.61' DEDICATED HEREIN. FND %" IRON PIN WO CAP, NORTH 0.09' OF BOUNDARY, FITS PIN FOUND PER RS 18647. (DAMAGED BADLY BY TO COMPUTED C.L. DETAIL "A" DEIAL "B" OF KAITLIN LN. SOUTH 2.37 N89° 32' 20"E 547.32' FND %" IRON PIN W ALUMINUM CAP MARKED "L.J FRIAR & ASSOC." 66.82 589° 32' 20"W 165.95' 10' PUÉ 10' PUE JACKSON COUNTY O SET %" X 24" IRON REBAR W PLASTIC CAP MARKED "HARDEY GROUP." SEE NOTE "A" RIGHT OF WAY PER 30.08: DETAIL "E" JCOR 2008-025685 LOT: 9 SET %" X 30" IRON REBAR W I &" ALUMINUM CAP LOT: I LOT: 5 (ALSO SEE DETAIL "A") 4496 SqFt 4502 SqFt 4898 SqFt MARKED "HARDEY GROUP." EXCEPTED TRACT PER SET %" X 30" IRON REBAR W PLASTIC CAP MARKED DETAIL "D" EXISTING 5' SLOPE JCOR 2015-030616 **EASEMENT** TRACT 2-RS 18647 92.061 100.04 92.05 (JCOR 2016-002153) 23 MONUMENT AS NOTED 589° 32' 20"W 589° 32' 20"W 589° 32' 20"W EXISTING 5' STORM DRAIN NORTH EASEMENT FND %" X 24" REBAR W YELLOW PLASTIC CAP MARKED "JACKSON CO ROADS & PARKS," PER RS EOUND %" IRON PIN W (JCOR 2018-010696) PLASTIC CAP MARKED "LJ N899 32' 20"E 172.05' LOT: 10 LOT: 6 FRIAR & ASSOC." (RS 17874) 4142 SqFt 4142 SqFt 165.05 (4" DEEP) $\Delta$ FND %" IRON PIN W ALUMINUM CAP MARKED LOT: 2 20 1 "NEATHAMER SURVEYING." (PER RS 19588) 4502 SqFt INITIAL POINT OF BEGINNING 92.06' 92.05 100.04 FND %" IRON PIN W YELLOW PLASTIC CAP MARKED 200 200 200 200 200 93.01 ▲ "#2011" PER RS 17591, N 0.07' OF BOUNDARY. (4" DEEP) 589° 32' 20"W 589° 32' 20''W 589° 32' 20"W 7633 SqFt PUE = Public Utility Easement to include electric, telephone, LOT: 7 - FIRE DEPARTMENT Ω. LOT: II cable television, sanitary sewer, water and storm drain. LOT: 3 27.5 27.51 4142 SqFt TURNAROUND 4143 SqFt 4502 SqFt RS = Jackson County Recorded Survey No. 5' PSDE CENTERED EASEMENT (FDTE) 43.151 ON LOT LINES LOT: 13 MWC = Medford Water Commission 4.TT 589° 32' 20"W 5458 SqFt 92.05 N89° 32' 20"E JCOR = Official Record of Jackson County Oregon 100.04 10' PUE N46°34'47"W 0 589° 32' 20"W 92.161 589° 32' 20"W PC = Point of Curvature - Start Horizontal Curve 10' PUE LOT: 15 47.03' 25 7229 SqFt PT = Point of Tangency - End Horizontal Curve 89.44' LOT: 12 10' PUE-LOT: 8 LOT: 4 PCC = Point of Compound Curvature 4326 SqFt 589° 32' 20"W SHADED AREA INDICATES 4148 SqFt WOOD FENCE 4508 SqFt 7' WIDE RIGHT OF WAY COM = City of Medford S.D.E. <del>| | 3</del>0' AVERAGES DEDICATED HEREIN IO' PUE 0'-05' WEST PSDE = Private Storm Drain Easement 102.96 27.50' 27.50' -92.051 100.04 201.61' 170.60' PRC = POINT OF REVERSE CURVE I' STREET/ SDE = STORM DRAINAGE EASEMENT DEDICATED TO CITY ·589° 32' 20"W 565.32 WOOD FENCE WOOD FENCE WOOD FENCE 26 OF MEDFORD PER THIS PLAT. **AVERAGES** AVERAGES O.I' DETAIL "C" AVERAGES C.L. = CENTERLINE 0.2' SOUTH SOUTH 5**0** 0'-02' SOUTH S.E. = SLOPE EASEMENT CHAIN LINK FENCE FND %" IRON PIN WITH ORANGE PLASTIC CAP FND %" IRON PIN WITH JCOR 99-36453 AVERAGES 0.2'-0.3' ----- MWC EASEMENTS (JCOR 2018-013769) ORANGE PLASTIC CAP SOUTH MARKED "NEATHAMER MARKED "NEATHAMER FROM WHICH A FOUND -HERITAGE PLACE I — SUBDIVISION LOTS, LAYER S-LOTS SURVEYING" PER RS 19955 %" X 24" REBAR W YELLOW SURVEYING" PER RS 19955 PLASTIC CAP MARKED --- IS THE BOUNDARY OF THE PLAT (8" DEEP) (8" DEEP) \* RECEIVED \* "JACKSON CO. ROADS & PARKS" BRASS CAP DATE <u>8/6/19</u> BY <u>PB</u> PER RS21042, FLUSH WITH -BEARS N35° 38' 17" W, 0.27' PAVEMENT Curve Table Curve Table This survey consists of: MARKED 3\_sheet(s) Map Length Chord Length Length Radius Curve # Chord Direction Chord Length Chord Direction Radius Delta DLC 188 page(s) Narrative 20.00 87° 50' 50" 544° 01' 05"W 30.66 46.53 119.00 513° 25' 06"E 22° 24' 13" 46.24 JACKSON COUNTY REGISTERED 2012 13.57 10° 43' 18" 55° 15' 59"E 72.50 13.55 C34 24.85 16° 33' 19" 58° 11' 00"E 24.76 86.00 **PROFESSIONAL SURVEYOR** TO DISTU LAND SURVEYOR 550° 32' 39"E C28 27.87 20.00 79° 50' 02" 25.67 525° 07' 33"E *C3*5 26.01 86.00 17° 19' 48" 25.91 1" = 40'39.51 C29 90° 33' 20" N45° II' 00"W 25.00 35.53 1.73 114.00 0° 52' 04" N33° 21' 25"W NOTE "A" - FOUND %" IRON PIN W/ HARDEY GROUP, INC C30 39.03 25.00 89° 26' 40" 544° 49' 00"W 35.18 51.84 514° 45' 22"E C37 100.00 29° 42' 05" 51.26 YELLOW PLASTIC CAP MARKED OREGON "NEATHAMER LS 2675" PER RS 18647, 39.51 25.00 90° 33' 20" N45° 11' 00"W 35.53 C38 44.26 90° 33' 40" 544° 49' 00"W 39.79 P.O. BOX 1625 28.00 JULY 16, 1982 MEDFORD, OREGON 97501-0063 BORE N45° 24' 36" E, 0.09' - POINT WAS JOHN HARDEY C32 4.80 119.00 2° 18' 40" 51° 03' 40"E 4.80

DESTROYED BY CONSTRUCTION.

37 2W 23 DC of Tax Lot 1600

VOICE: 541-772-6880

EMAIL: info@hardeygroup.com

SHEET 2 OF 3

1990

RENEWS: 6-30-2019