

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

Survey for: Steven and Valerie Rinkle

30 S. Barneburg Road Medford, Oregon 97504 **Daveid Viggiano** 36 S. Barneburg Road Medford, Oregon 97504

Location:

A portion of Lot 6, Block 4 of **SISKIYOU HEIGHTS ADDITION** in the Northwest one-quarter (1/4) of Section 29, Township 37 South, Range 1 West, Willamette Meridian, City of Medford, Jackson County, Oregon.

Purpose:

To survey, monument and record a map of Survey for City of Medford Planning File No. PLA-19-00077. The properties involved are described in Documents No. 97-45180 and 2017-039618, Official Records of Jackson County, Oregon. The adjustment is to remedy a setback issue with an existing structure.

Procedure:


I found original monuments from SISKIYOU HEIGHTS ADDITION. I proportioned the distance to establish the Northeast corner of Lot 6 in Block 4 which is the referenced point of commencement of the legal descriptions effecting tax lots 5900 and 6000. From that point I used the record bearing and distances of Document No. 97-45180 to establish the East, South (except for the adjusted potion). West and North boundaries of tax lot 5900. The found 3/4" iron pipes at the Northeast and Southeast corners are of unknown origin. I concluded the found D.McMahan pin near the Northeast corner was too far out of position to be accepted as the true corner. The D.McMahan pin near the Northwest corner that is not of record was found to have been set in 1997 in conjunction with a Property Line Adjustment between tax lots 5800 and 5900. Deeds were prepared, signed and recorded by both property owners (97-45180, 97-45181 and 97-45182). While monumenting property without filing a map of survey is a violation of Oregon Revised Statute 209.250, it should not invalidate the Property Line Adjustment. The East, West and North boundary lines for tax lot 6000 are identical in bearing to those established for tax lot 5900. I established the South line as being parallel to the unadjusted portion of the North line in order to keep the 80.00 foot call of the original deeds. I have no knowledge of the origin of the 5/8" pin at the Southwest corner.

Basis of Bearing:

West line of S. Barneburg Road per Survey No. 15297.

Date:

March 4, 2020



DAVID B. SERECI

David M. Minneci L.S. 2349 - Oregon Expires 12/31/20 880 Golf View Dr., Ste. 201 Medford, Oregon 97504

(19059nar.doc)