Approvals:	, ,		
Jackson County Development Services Approval: Approval: Jackson County Planning Director Warager Planning Action No. 439-18-00083-SUB			
lackeon County Surveyor. Jett Jen			
Examined and Approved this day of April, 2021.			
Jackson County Surveyor File No. <u>23339</u>			
Recording:	. 444		and recorded go
Filed for record this 17th day of Man, 2021 at 1:21 o'clock f.m and recorded as Partition Plat No. P-16-2021 of the Records of Partition Plats in Jackson County, Oregon, Index Volume 32, Page 16.			
Christing Walker Depu	myo J. Morga		
Tax Statement Approval:			
All taxes, fees, assessments, or other charges as required by O.R.S. 92.095 have been paid as of May 14th , 2021.			
Halw Deras	5/14/2021		
Tax Collector	Date		
With	8/14/202		
Assessor	Date		
DECLARATION			sha landa haraan
KNOW ALL MEN BY THESE PRESENTS, that described and have partitioned the same of the lines are plainly set forth and that and establish the Private Ingress/Egress (create and establish a Private Irrigation E	t this plat is a correct repres	sentation of the partition.	We do hereby create arcel 2. We do also
	7/1		
MA MITTO	Menul	<i></i>	
Erik J. Glatte	Ingum Skjervold		
State of Oregon)			
SS			
County of Jackson)			
Personally appeared the above named Eri their voluntary act and deed.	k J. Glatte and Ingunn Skjerv	old who acknowledged the f	oregoing to be
Before me: Hunnette M. Center	Date: <u>4/2/2021</u>	_	
Jeannette M. Center, NOTARY PUBLIC-OREGON Commission No. 469047 My Commission expires: November 21, 2021			
I hereby certify that this plat is an exact copy of the original Paul A. L. S. Surveyor	**RECEIVED** Date 3/17/21 By 3F This Survey Consists of: 2 sheet(s) Map page(s) Narrative JACKSON COUNTY	REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 30, 1976 HAROLD L. CENTER	SURVEYOR HAROLD L. CENTER 2604 David Lane Medford, OR 97504 Phone 541-535-6108 Oregon Certificate No. 1071
/	SURVEYOR	1071	-

38 1W 35 200 File: GLATTE_18-19

Renews: /2/31/2/

PARTITION SURVEY
PARTITION PLAT NO. P-16-2021
JACKSON COUNTY OREGON
LOCATED IN

Sheet 1 of 2

EAST 1/2 SECTION 35
TOWNSHIP 38 SOUTH, RANGE 1 WEST, WILLAMETTE MERIDIAN
JACKSON COUNTY, OREGON

FOR
ERIK J. GLATTE AND INGUNN SKJERVOLD
7715 RAPP LANE
TALENT, OREGON 97540
DATE: FEBRUARY 20, 2021

SURVEYOR'S CERTIFICATE

I, Harold L. Center, duly Registered Professional Land Surveyor of the State of Oregon, do hereby certify that this map correctly represents a survey made by me and complies with the regulations for land partitions and the following is an accurate description of the parent tract of land surveyed and described in document 2020-08337 Official Records of Jackson County, Oregon as set forth

Beginning at the most easterly—southeast corner of Donation Land Claim No. 67, Township 38 South, Range 1 West of the Willamette Meridian in Jackson County, Oregon thence North 0°13′33″ West (record North) along the easterly line of said Donation Land Claim 293.00 feet to a 5/8 inch diameter iron pin, said iron pin marking the westerly point of the Boundary Line Agreement recorded as document 2021—005144 Jackson County, Oregon Official Records, thence along the Boundary Line Agreement South 89°47′19″ East 396.14 feet to a 5/8 inch diameter iron pin; thence continue South 89°47′19″ East 21.36 feet to a 5/8 inch diameter iron pin; South 89°47′19″ East 242.50 feet to a 5/8 inch diameter iron pin; thence continue South 89°47′19″ East 599.28 feet to a 5/8 inch diameter iron pin witness corner to the East line of Government Lot 4, Section 35, Township 38 South, Range 1 West, Willamette Meridian, Jackson County, Oregon, thence South on the East line of Government Lot 4 293.00 Willamette Meridian, Jackson County, Oregon, thence South on the East line of Government Lot 4 293.00 feet more or less to a point South 89°47′19″ East 20.00 feet more or less from a 3/4 inch diameter iron pin witness corner; thence North 89°47′19″ West 20.00 feet more or less to said 3/4 inch diameter iron pin; thence from said witness corner monument North 89°47′19″ West 842.82 feet to a 5/8 inch diameter iron pin; thence North 89°47′19″ West 417. 50 feet to the point of beginning. Contains 8.61 acres of land more or less.

HAROLD L. CENTER, P.L.S.

Peb. 20, 202

Date

Survey Narrative To Comply With Paragraph 209.250 Oregon Revised Statutes

Purpose; To survey and partition of the land described within deed document 2002-08337 according to client's direction and approved planning action by the Jackson County Development Services planning action No. 439-18-00083-SUB.

I began this survey with a review of the property description Corners of Doantion Land Claim No. 67 controlled the westerly line of the subject property, the required Donation Land Claim corners were found to be existing monumented points. Further review of the description indicated the subdivision of Section 35 would be required due to deed boundaries described by the government lot lines controlling the boundaries of mutiple properties within the area. The east one-quarter corner of Section 35 had been recovered and re-monumented. The west one-quarter of Section 35 had not been recovered and I found no record of any surveys being performed referencing ties to the west one-quarter corner.

A review of the prior filed surveys No. 3419 and 4989 indicated the controlling lines along the north and east boundaries of the subject property could not be determined. Surveyor Charles H. Hurst in performing survey No. 3419 established "witness corners" and states the proper survey required to locate the boundaries "not economically feasible".

Surveyor Mark E. Boyden in performing survey No. 4989 utilizes the old existing fence along the north boundary of the property he surveyed adjoining my client's south boundary. I performed survey ties to the old fence and Boyden's witness corner to the east. I agree with Boyden's decision to hold this fence line.

An old fence also existed along the north line of my client's property. I performed survey ties to said fence line and determined the fence to be essentially parallel to the fence along the south line. The north/south distance between the two fence lines is 293 feet. The record distance between the East—South—East Donation Land Claim Corner and the North line of Government Lot 4 is 4.5 chains or 297.00 feet. The recommended solution was a Boundary Line Agreement utilizing the fence and holding the 293.00 foot width. Each landowner reviewed the fence line and agreed between the property owners to establish monuments along the existing fence line and to fix the boundaries by mutual Boundary By Agreement 2021—005144.

Equipment Utilized This Survey: Nikon DTM 520 Electronic Total Station, Leica GS 14 GNSS Receiver, Verizon MIFI connection for RTK solutions and related equipment.

