5.30 5.29 1/4 COR. 5.31 S. 32 178.80 5.32 Take To FAOCISE DIVER 5 89°49'50"W 242.54 447.78 5 89 49 50" W 605.00' -107.63 971± N 89°48'00" W 330.00" 5.31 1/4 COR. S 89°53'30" W CENTER SEC.32 589.97 5.32 RECEIVED

SURVEY IN N.W. 1/4 SEC. 32 T.35S, R.I.W., W.M.

FAYDREX INC.

66-28

BY EDWARD MCGINTY

MEDFORD OREGON

JANUARY 1967

• = 2"I.PIPE FD.

SCALE 1=200'

o = 5/8"I.PIN SET

= 3/4"I PIPE FD.= 1"I.PIPE FD.

RECEIVED
MAY 15 1967

SURVEYOR



- 153 153 - **3** 

Survey No. \_

Survey Narrative to comply with O.R.S. 209-250:

Survey for: Faydrex, Inc.

1054 S. Riverside Ave. Medford, Oregon 97501

Survey by: Edward A. McGinty, L.S.

Medford, Oregon

Jan. 1967

BASIS OF BEARING: Previous survey and solar obser.

## PRECEDENCE OF SURVEY:

- 1. Found a 3/4 in. iron pipe, 6 ins. deep, older calls for stake and mound of stone, (This point falls in a field and the stones were probably removed) being 38.5 ft. south of the NE. cor. of the SW 1/4 of the NW. 1/4. This monument agree's within approx. 3.0 ft. of old deed record distance and agree's almost identically with the newer Deed record distance which refers to older deeds.
- 2. Deed calls for iron pin, finding a 3/4 in. iron pipe, approx. flush which agrees closely to deed calls to said point from monument found at Pt. 1:
- 3. Older calls for anchor post (note, a new fence now exists here) New deed calls (Vol. 551 page 505) for a 3/4 in. iron pipe which was found and identified by adjacent wwner.

Other monuments set on this survey, being 3/4 in. iron pins X 24 ins., set flush with the surface.

RECEIVED
MAY 1 5 1967

SURVEYOR

REGISTERED
OREGON
LAND SURVEYOR

Thurd A. M. Hasiny
301

66-28