



Survey For:
 A. F. DRESSLER
 Located in D.L.C. No. 39,
 in the N.W. 1/4 Sec. 29,
 T. 37S.R.2W., W.M.
 By: Mark E. Boyden
 Oct. 24, 1968

SCALE: 1" = 100'

- set 5/8" X 24" i. pin flush
- ✱ set 5/8" X 30" i. pin flush unless otherwise indicated
- found monument as indicated

Basis of Bearings:
 Recorded Survey
 No. 3132

REGISTERED
OREGON
 LAND SURVEYOR
Mark E. Boyden
 NOVEMBER 2, 1951
MARK E. BOYDEN
 281

JACKSON COUNTY
 RECORDED
 NOV 12 1968
 SURVEYOR

19 20
 30
 South 558.96 meas.
 Record= South 562.44
 Sec. Cor.
 fd. 2" i. pipe flush
 3872
 N 85° 27' 20" W 354.25'
 R=20.00' L=22.56'
 R=230.00' L=128.72'
 S 85° 27' 20" E 206.47'
 84.53'
 15.18'
 L=95.14' R=170.00'
 exp. 4"
 fd. 3/4" i. pipe exp. 5"
 N.E. cor. Recorded Survey No. 887
 331.99'
 (Record= East 539.18')
 S 0° 08' 50" E
 (Record= N 0° 14' E, 557.07')
 455.35'
 455.35'
 ROAD
 R=180.00' L=166.30'
 R=20.00' L=36.24'
 L=108.7'
 R=20.00' L=26.59'
 exp. 12"
 exp. 6"
 exp. 12"
 N 53° 23' 20" W
 S 53° 23' 20" E
 R=20.00' L=36.24'
 S 0° 27' 10" E 190.70'
 N 0° 27' 10" W 215.28'
 S 76° 38' 20" E 102.97'
 N 13° 21' 40" E 60.00'
 N 76° 38' 20" W
 fd. 1/2" i. pipe flush
 fd. 1" i. pipe flush S.W. cor. Recorded Survey No. 887
 225.00'
 S 76° 45' 50" E 236.42'
 N 0° 08' 50" W 225.00'
 236.42'
 27.55'
 N 76° 45' 50" W 462.43' meas.
 (Record= S 76° 23' E, 462.56')
 N 0° 08' 50" W, 61.67'
 fd. 1/2" i. pipe flush
 LIVINGSTON ROAD
 3872
 fd. 1/2" i. pipe flush

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

FOR: A. F. Dressler
4028 Livingston Road
Medford, Oregon 97501

PURPOSE: (1) To monument and describe a residence tract within
the A. F. Dressler ownership fronting Livingston Road.
(2) To monument the boundaries of a proposed road.

PROCEDURE: Ties were made to monuments previously set by Surveyor
L. E. Ager for control of Livingston Road, to monuments set on Recorded
Survey No. 887, and to the Re-established Section corner common to Sections
19, 20, 29 and 30. Also angular ties were made to controls previously
set by this office on Old Stage Road on Recorded Survey No. 3132 to determine
an acceptable meridian.

Utilizing the boundary monuments previously set by Ager for
control, monumented the tract and road as shown on the map to accompany
this report.

October 24, 1968

