
# MINOR LAND PARTITION

LOCATED WITHIN D.L.C. NO. 42, SECTIONS 9 and 10
TOWNSHIP 38 SOUTH, RANGE I WEST, WILL AMETTE MERIDIAN
CITY OF PHOENIX, JACKSON COUNTY, OREGON



Robert Josh wille

FOR:

Paul D. Williams 8909 Yank Gulch Road Talent, Oregon

### SURVEYOR'S CERTIFICATE:

I, Robert Joseph Milts, registered surveyor of the state of Oregon, certify that this map correctly represents the survey made under my direction and complies with the regulations of Minor Land Partitions.

Robert Joseph milte

Al	PP	RO	VA	1	
			,,	_	

By:	RI	LL	$\mathcal{L}$	Date: 1/26/8
City of Phoenix	Plannina De	pt		July - 1 - 1

Jackson County Surveyor, by Deputy	Date: 11/21/80
Jackson County Surveyer, by Deputy	

By: Walte 9. City Engineer	M	anguere	Date: 11/18/80
City Engineer		0	Dule.

## RECORDER'S CERTIFICATE:

Filed for record this 30th day of January, 1981, at 11:35

O'Clock A.M. and Recorded in Volume 3 at Page 93 of

"Minor Land Partitions" in Jackson County, Oregon.

Waldene Terry Pauline & Mc Connack

#### PREPARED BY:

I HEREBY CERTIFY THAT THIS IS AN EXACT COPY OF THE ORIGINAL.

Marquess and Associates, Inc. 1120 E. Jackson St. Medford, Oregon

DATE: November 19-80

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR: Paul D. Williams 8909 Yank Gulch Road Talent, Oregon

LOCATION:

Being within Donation Land Claim No. 42, Sections 9 and 10, Township 38 South, Range 1 West, Willamette Meridian, City of Phoenix, Jackson County, Oregon.

PURPOSE:

To partition off an approximately one acre parcel from the client's land, which is Tax Lot 201, Map 38 1W 9A and Tax Lot 2901, Map 38 1 W 10. This survey also establishes a portion of the right-of-way line for Luman Road, as acquired by the State of Oregon by O. R. 72-10667.

PROCEDURE:

The location for the Luman Road right-of-way was calculated from the coordinates shown on the Oregon State Highway right-of-way drawing No. 8B-10-21. The State bearings have been rotated to the bearings shown on Recorded Survey No. 3461. The coordinates were translated by calculating the location of the easterly line of R. S. 3461 near P. C. S. 1036+49.56. The measured distance shown on the attached map from the found pin on the easterly line, to the found monument at P.T. 1038+99.56 agreed with its calculated position.

After consulting with the Jackson County Public Works Department regarding the right-of-way location for Fern Valley Road, this office decided that the monuments set by R. S. 3461 were probably the best evidence available between Church St. and the east side of I-5, and therefore have been used.

The southerly and westerly lines of Tax Lot 201, Map 38 1W 9A, have not been determined by this survey.

January 31, 1981

JAN 3 0 1981

MARQUESS & ASSOCIATES, INC. Consulting Engineers Medford, Oregon

REG ON SEPTEMBER 23, 1977
ROBERT JOSEPH MILTS
No. 1270

REGISTERED

PROFESSIONAL

rec

AND SURVEYOR

Robert Joseph Milts Professional Land Surveyor