

MAP OF SURVEY

LOCATED IN

S.W. 44 S.E. 14, SEC. 18, T. 385., R.IW., W.M.

JACKSON COUNTY, OREGON

FOR

SEE NARRATIVE FOR NAMES & ADDRESS

SCALE: 1"= 200"

LUNE 19, 1981

BASIS OF BEARING R.S. No. 249

• = SET 5/2" × 24" IRON PIN

O = FOUND I" IRON PIPE PER R.S. No. 249

PROFESSIONAL LAND SURVEYOR

Harry L. Lake

OREGON JANUARY 12, 1962 HARRY L. LAKE No. 564



38 IW 18

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209,250 OREGON REVISED STATUES

CONSOLIDATED SURVEY FOR:

Robert F. Baylis 2011 Pioneer Road Medford, Oregon 97501

David H. Scafani 416 Greenbrae Drive Medford, Oregon 97501

Harry E. Krumlauf, Jr. 4021 Pioneer Road Medford, Oregon 97501

Richard D. Walker 4031 Pioneer Road Medford, Oregon 97501

Anthony P. Scafani 2117 Hillcrest Road Medford, Oregon 97501

LOCATION:

Southwest one-quarter (%) and the Southeast (%) of Section 18, Township 38 South, Range 1 West, Willamette Meridian, Jackson County, Oregon.

PURPOSE:

To survey and monument the properties of the above named owners as shown on the attached map as per client's request. All properties have existing tax lot numbers.

PROCEDURE:

Established Pioneer Road right of way using 2"x 4" wood right of way markers set by Jackson County personnel at stations 134+00 and 147+00. The road center line references could not be found. The road center line bearing used for this survey is South 62°11'30" East (Jackson County Road Department bearing for same is South 62°15'30" East). Control for this survey is based on Recorded Survey No.

249. Set monuments as shown on the attached map.

Basis of Bearing:

Recorded Survey Number 249

June 19, 1981

RECEIVED JUN 1 9 1981 SURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR Harry L. Lake OREGON
JANUARY 12, 196
HARRY L. LAKE
NO. 564