

Survey Narrative Don Buchanan Page 2


located at the Southeast corner of Lot 4, Block 'A'. These monuments were not tied co-ordinately at that time. The departure for the Northeast corner of Lot 3 was proportioned in between a point 60.06 feet Easterly from the 5/8" iron pin located at the Southeast corner of Lot 4, Block 'A' and the proportionate position for the Northeast corner of Lot 4, Block 'C'. It should be made clear at this time that the South boundary of Lot 2 does not necessarily run along this line (though it will be very close). The exact latitude position for the Northeast corner of Lot 3 has not been thoroughly investigated. The latitude position is not necessary at this time to determine the bearing of the East boundary of Lot 3.

The North boundary of the tract described in Volume 378, Page 395 D.R. was established parallel with the South boundary of Lot 3 running from the East boundary of Lot 3 at a point 238.27 feet Northerly along said East boundary from the 1/2" iron pipe found set for the Southeast corner of Lot 3. This procedure agrees with the position of the boundary dividing the North-half and South-half of Lot 3 as described in Volume 378, Page 395 D.R. (South-half) and Volume 408, Page 61 D.R. (North-half). There is a chain link fence approximately 2 feet South from the Deed Record position of this boundary.

The boundary between Parcel 1 and Parcel 2 was established per the client's directions.

Basis of bearings is Filed Survey No. 7892.

March 29, 1982



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 16. 1967
GARY D. KAISER
NO 803

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

FOR:

Don Buchanan

383 Red Blanket Road Prospect, Oregon

BY:

Boyden Surveyors 108 Mistletoe Street Medford, Oregon

PURPOSE:

To monument and describe two parcels as approved for partition by the Jackson County Department of Planning and Development (see File No. 82-19-MP), being a portion of Lot 3, Block 'C' of PROSPECT TRACTS (a recorded subdivision). This being a Class "A" division, all parcel corners were monumented.

The partitioned parcel is that portion of the tract described in Volume 378, Page 395 D.R. lying Westerly from the West boundary of that parcel described in Volume 579, Page 89 D.R.

PROCEDURE: Utilizing a one-second theodolite and EDM equipment, a traverse was run around Block 'C' and the monuments indicated as found on the annexed map were tied. The corners of Lot 2 and the Northeast corner of Lot 3 have all apparently been destroyed. The Easterly boundary of Lot 3 is prime control needed to locate the Westerly boundary of that tract described in Volume 579, Page 89 D.R. The following procedures were utilized to establish the Easterly boundary of Lot 3:

- A. A position for the angle point on the Easterly boundary of Lot 2 was calculated by the broken boundary method between found monuments located at the Southeast corner of Lot 4 and the Northeast corner of Lot 1. Once this point was determined, the Northeast corner of Lot 4 was proportioned in.
- B. In our process of tying control utilized to establish the Highway right-of-way lines on Filed Survey No. 740 (which is the same Highway right-of-way control utilized at this time), the 1/2" iron pipe then located at the Northwest corner of Lot 3 (now destroyed) was found to be 60.06 feet Easterly from the found 5/8" iron pin